Risk Assessment

RISK RATING = LIKELIHOOD* CONSEQUENCES

A likelihood of occurrence		B Consequences (Injury severity)	
Almost certain	5	Extreme	5
Likely	4	Major	4
Possible	3	Moderate	3
Unlikely	2	Minor	2
Rare/Remote	1	Negligible	1

Risk classification	Risk value
High	16-25
Medium	9-15
Low	1-8

5*5 Risk Matrix					
5	5	10	15	20	25
4	4	8	12	16	20
3	3	6	9	12	15
2	2	4	6	8	10
1	1	2	3	4	5
	1	2	3	4	5

HIGH	The risk should ceased immediately until further control measures to mitigate the risk are introduced.
MEDIUM	The risk should only be tolerated for short term and then only whilst further control measures to mitigate the risk are being planned and introduced, within a defined time period.
LOW	Are largely acceptable, subject to reviews periodically, or

Project Name	Potential Hazard	Possible Result (Injury/ Damage/ Loss)	Risk Evaluation			SWP (Safe work procedure)	Control (Supervision/ register)
			A	B	R		
A. Working on Unprotected Slab edges	• Falling from heights OSHA's fall protection standard: Each employee on working surface between 6 and 15 feet from the edge, you will need standard fall protection, including Guardrail and fall arrest.	• Fatal injury (Including death)	4	5	20 20 = HIGH RISK	• Maintain Guardrail to protect workers from falling down. • Provide strong barricades to close slab peripheries. • Provide Toolbox briefings. • Post warning signs and use warning tapes.	• Site safety representative (Site Engineer) • Forman • EHS Engineer

B. Working on Unprotected Staircases  	• Falling from heights The 6-foot rule: Workers requires the use of fall protection when construction workers are working at heights of 6 feet or greater above a lower level.	• Fatal injury (Including death	3	4	12 12 = MID RISK	• Maintain Guardrail to protect workers from falling down. • Provide strong barricades to close slab peripheries. • Provide Toolbox briefings. • Post warning signs and use warning tapes.	• Site safety representative (Site Engineer) • Forman • EHS Engineer
C. General Housekeeping 	• Slip • Trip • Fall hazards and • Material damage OSHA's crane standard: All places of employment, passageways, storerooms, service rooms, and walking-working surfaces are kept in a clean, orderly, and sanitary condition.	• Abrasion, and bleeding • Property damage.	3	2	6 6 = LOW RISK	• All passageways, gangways and access ways shall be kept free of materials, supplies, and obstructions at all times. • Tools, materials, extension cords, hoses, or debris shall not cause tripping or other hazards. • Material shall stack properly. • Avoid corrections and damage to the property.	• Site safety representative (Site Engineer) • Forman • EHS Engineer