

Stage 1: Balancing
Stage 2: Refining
Stage 3: Converging
Error (p.u.)
10^{1}
1
10^{-1}
10^{-2}
10^{-3}
10^{-4}
10^{-5}
0
0
200
400
600
800
1000
Iteration steps
Feasibility Error (raw)
Optimality Error (raw)
Feasibility Error (moving average)
Optimality Error (moving average)