Laser settings:

Speed (16%)

Power (80%)

thickness (0.063")

middle layer window slot. To ensure proper fitting, test cut

small batch and adjust settings

until fit is good. YMMV.

Note: part should press-fit into