B&R Revision Information VisualComponents SG4 Runtime Upgrade 3.96.4 07–Jul–2015

i

Contents

SG4 Runtime Upgrade 3.96.41
1
1
3
3
3
3
3
3
3
4
4
6
6
7

B&R Revision Information (07.07.2015) VisualComponents SG4 Runtime Upgrade 3.96.4

The current revision information can be downloaded from the B&R Homepage download area (http://www.br-automation.com/en/downloads).

Contents

- Requests and problems by version
 Requests and problems by product/component

Requests and problems by version

ID	valuation	solved since	known since	Description
400071755	Problem	_	VC 3.73.4	Panel not reinitialized after a lost connection
400112360	New function	VC 3.96.1	VC 4.05.1	Function for reading the limits of a data point
400153604	Problem	VC 3.96.4	VC 3.96.3	Page change in VC 3.96.3 with AR C4.01 incredibly slow
<u>400115430</u>	Problem	VC 3.96.4	V3.00.90.30 SP0x	Guaranteed correct initialization sequence of visapi and viscomp modules VC3 handle is returned.
400131837	Problem	VC 3.96.3	VC 4.05.6	Continuous user trend fluctuations with SampleRate <1 (milliseconds not taken into account on display)
400129423	Problem	VC 3.96.3	VC 3.96.2	Special characters not displayed on panel 4B1270.00–K36.
400133833	Problem	VC 3.96.3	VC 3.96.2	Trend > Scale > Scroll > Mode Factor, faulty time specified after scrolling
400133833	Problem	VC 3.96.3	VC 3.96.2	VC4 > Trend > Scale > Zoom > Span mode – TimeSpanDatapoint overflow
400128245	Problem	VC 3.96.3	VC 3.96.2	Page fault if trend data (trend curve) configured multiple times in a trend
400121179	Problem	VC 3.96.3	VC 3.96.1	VC4 > Trend time drifting with respect to system time
400123606	Problem	VC 3.96.3	VC 3.96.1	Trend > ValueScale > MinValue = 0, MaxValue = 0.6-0.9 > Values not displayed
400101336	Problem	VC 3.96.3	VC 3.95.7	Rounding errors visible between time scale and value if the number of displayed values (<50) is reduced
400087974, 400050060, 400028969	Problem	VC 3.96.3	VC 3.95.5	Overflow when synchronizing the trend with the system clock if Sample Rate > 32535
400087974, 400050060, 400124149, 400125253	Problem	VC 3.96.3	VC 3.95.5	Overflow when synchronizing the trend with the system clock if Sample Rate > 32535
400081836, 400083464	Problem	VC 3.96.3	VC 3.95.3	Trend updated too often and CPU load at 100% when setting AutomaticScrollOffset to 0
400078084, 400091350, 400139741	Problem	VC 3.96.3	VC 3.95.0	Value change in user trend data causing reset of zoom settings
400125616	Problem	VC 3.96.3	V3.00.90.27 SP0x	Possible to trigger any key functions when using extension keys with handwheel (using the handwheel), such as the 5AC800.EXT1–K02
400124119	New function	VC 3.96.3	nicht relevant	Trend > ValueScale > MaxValue= 9-6, unnecessary decimal places (since always zero) displayed
400122618, 400122696, 400125727	Problem	VC 3.96.2	VC 3.96.1	VC4 > Trend (type: Online): Relative time displayed beginning with 0 on the time axis (should be current time)
400115707	Problem	VC 3.96.2	VC 3.96.0	VC3 > VA_SetBrightness / VA_SetContrast adding the 0 character (ASCII 0x30) to the text field until the end of the line if one of the functions is called with the value 100
400119167, 400119471, 400125693	Problem	VC 3.96.2	VC 3.96.0	Corrected page fault when changing the line in the alarm list several times
400116902	Problem	VC 3.96.2	VC 3.96.0	Switching pages sometimes resulting in page fault when using VC_Saccess / VC_Srelease in several user programs
400118912	Problem	VC 3.96.2	VC 3.96.0	System pushed to the limit with VNC visualization with large trend, small sample rate and 32-bit color depth
400116355	Problem	VC 3.96.2	VC 3.95.9	GET_CONTRAST request handled in display driver
400116355	Problem	VC 3.96.2	VC 3.95.9	VA_GetBrightness() function implemented
400117729	Problem	VC 3.96.2	VC 3.95.9	VC4 TargetResourceRoot > Error replacing texts (individual texts are not replaced)
400112317	New function	VC 3.96.1	VC 4.05.1	Request > Vclib > Getting limits of a numerical input field
400116721. 400119206	Problem	VC 3.96.1	VC 3.95.9	Trend control (Type: User) shows current time on time scale axis if no SampleDateTimeDatapoint is connected.
400115140. 400119471	Problem	VC 3.96.1	VC 3.95.8	Page fault when using VA_TextOut extensively
400114025	Problem	VC 3.96.1	VC 3.95.8	SXGA resolution 1280 x 1024 with 32-bit color depth now supported
400106404	Problem	VC 3.96.1	VC 3.95.6	Invalid value in pv-description field
400082576	Problem	VC 3.96.1	VC 3.95.3	Status of LEDs on the MP50 not updated on lost connection
400108187	Problem	VC 3.95.9	VC 3.95.8	Errorhandling width VcScrSht is important
400110961	Problem	VC 3.95.9	VC 3.95.8	Full HD resolution is scaled on the APC810 GM45 CPU when operated on an AP830
400110682	Problem	VC 3.95.9	VC 3.95.8	display. VA_GetTouchAction hangs at status 1 (pressed) randomly when send event is delayed.
<u>400110682</u> <u>400109703</u>	Problem	VC 3.95.9 VC 3.95.9	VC 3.95.8	Exception when switching from terminal to administrator mode if ARwin is selected in the VC
400101767	Problem	VC 3.95.9	VC 3.95.7	Windows terminal but no boot loader is configured VCresman violated protected memory after restarting an HMI application. This error occurred if notifications of DP changes for the previous HMI application were not sent. This behavior

I	ı	i	I	L
400104823	Problem	VC 3.95.9	VC 3.95.6	has been corrected. Memory error when writing calibration data
400106379	Problem	VC 3.95.9 VC 3.95.9	VC 3.95.6	Bitmap with FillArea at position Left=-1 and Top=-1 causes PF (this faulty configuration can occur when replacing bitmaps).
400111493	Problem	VC 3.95.9	V3.00.90.25 SP0x	Hotspot catch release event when NumPad (overlay) is closed
400106979	Problem	VC 3.95.9	V3.00.90.24 SP0x	VC4 > Switching to trend page with disabled TrendValueScales (disabled by Runtime->StatusDatapoint) causes a page fault.
400109716	Problem	VC 3.95.9	V3.00.90.24 SP0x	VC4 > EditControl "Delete" command on the first line causes a page fault
400107408	Problem	VC 3.95.9	V3.00.90.24 SP0x	With the password control, the "HasFocus" flag is set in the status register although the control has been hidden with the "Hide" bit.
400107392	Problem	VC 3.95.9	V3.00.90.24 SP0x	VC4 > Alarm > WrapMode Endless causes PageFault after scrolling and ack one alarm
400103303	Problem	VC 3.95.8	VC 3.95.7	Repeated downloads of visualization cause warning 28715 (unable to create Rtk object)
400102814	Problem	VC 3.95.8	VC 3.95.7	Stack overflow when text snippets work with pos. or neg. infinity values for the float and double types
400100072	Problem	VC 3.95.8	VC 3.95.7	Error when setting the Numeric control to "Hide" with the touchpad during input
400102666	Problem	VC 3.95.8	VC 3.95.7	Selecting the rotated image has been corrected.
400097156	Problem	VC 3.95.8	VC 3.95.6	Key matrix resets properly after PLC restart now.
400091811	Problem	VC 3.95.8	VC 3.95.6	XGA resolution on an external monitor now working with APC510/511, APC620 and APC810
400101146	Problem	VC 3.95.8	VC 3.95.6	If a DP is connected to several user trends, they are not displayed correctly.
400087761	Problem	VC 3.95.8	VC 3.95.5	VA_GetAlarmCount returns the wrong value for vaALS_NOTACKNOWLEDGED
400065496,	Problem	VC 3.95.8	VC 3.73.0	Alarms set to Acknowledge=Required, are still shown in the active alarm list even if they are
<u>400082552</u> 400105632	Problem	VC 3.95.8	V3.00.90.24 SP0x	already inactive. Errors in trend display if two or more independent trends are configured on one time scale
400103032				
400097097	Problem	VC 3.95.7	VC 3.95.6	FB BatteryInfo doesn't work for APC810.HwGetBattStatus(2) must be used.
400089532	Problem	VC 3.95.7	VC 3.95.6	VC does not yet support APC51x devices
<u>400097367</u>	Problem	VC 3.95.7	VC 3.95.6	Changing pages while saving causes a "deadlock" (visualization freezes).
<u>400094505</u>	Problem	VC 3.95.7	VC 3.95.6	Trend grid background shown even though layer is hidden using status data point
400093073	Problem	VC 3.95.7	VC 3.95.5	24x PW35 on X2X don't work fully
400085328 400088591,	Problem	VC 3.95.7	VC 3.95.5	Trend -> CursorTime data points on the TrendTime scale are not scaled. Considerable performance increase with VC optimization // Difference between WinXP and
400089914	Problem	VC 3.95.7	VC 3.95.5	Win7 is only subjective
400082027	Problem	VC 3.95.7	VC 3.95.3	Bitmap display -> Page fault at page change when VNC client is connected
400086001	Problem	VC 3.95.7	VC 3.95.3	Page fault when the VA_SetBrightness function is called on a VCWT
400080579 <u>.</u> 400082643	Problem	VC 3.95.7	VC 3.95.0	VC_CopyMemoryToScreen only copies parts of the specified area when the display is rotated by 90° 270°
400079372	Problem	VC 3.95.7	VC 3.95.0	When the "insert" command is used to insert a text at the end, subsequent input in the Edit control is faulty.
400096559	New function	VC 3.95.7	VC 3.73.4	An error in the configuration of the default language causes the terminal target to freeze at 100% during booting.
400094705	Problem	VC 3.95.7	V3.00.90.22 SP0x	APC51x not supported by VC
400087835. 400087699	Problem	VC 3.95.6	VC 3.95.5	Transfer error when VA_GetActiveAlarmCount or VA_GetAlarmCount are called in a user task
400083646	Problem	VC 3.95.6	VC 3.95.3	Internal VC4 IP address data point not shown for X2CP1485 CPUs
400083204	Problem	VC 3.95.6	VC 3.95.3	Error in VA_AlGetCurPos on the terminal when changing the page
400077803, 400092481	Problem	VC 3.95.6	VC 3.95.0	FB BatteryInfo doesn't work for APC810. HwGetBatteryInfo must be used.
400077340	Problem	VC 3.95.6	VC 3.95.0	With a very small string control (ControlWidth < CharWidth) and TextLengthOverrun Cut = True the program runs in an endless loop (100% usage)
400081712	Problem	VC 3.95.6	ARSG4_4.00.16_P04.00	Problems with ARwin in Windows 7 when firewall is on
400083974	Problem	VC 3.95.5	VC 3.95.4	Error saving the brightness/contrast settings in the file VcData if there is no touch screen
400082098	Problem	VC 3.95.5	VC 3.95.3	calibration data. VC Windows Terminal: Unhandled exception after reinstall
400082098	Problem	VC 3.95.5 VC 3.95.5	VC 3.35.4	Date/Time display in the Alarm control doesn't release internal memory for empty format
				String.
400075434	Problem	VC 3.95.4	VC 3.95.3	VC ProjectLoader freezes or crashes when a visualization application is loaded Loading BR modules to the terminal freezes (progress bar stops at x%) or the loaded BR
400080360	Problem	VC 3.95.4	VC 3.95.3	modules are defective
400078529	Problem	VC 3.95.4	VC 3.95.0	Error in repaint
400079295	Problem	VC 3.95.4	VC 3.95.0	When the IPAddress data point is written cyclically, the touch pad keeps closing
400076230	Problem	VC 3.95.4	VC 3.95.0	Incorrect display in DropDown control Panel hebind a bus controller sometimes not initialized after a power failure or a lost bus
<u>400071755</u>	Problem	VC 3.95.4	VC 3.73.4	Panel behind a bus controller sometimes not initialized after a power failure or a lost bus connection
400078627	Problem	VC 3.95.3	VC 3.95.0	Version number of VC3 modules not displayed correctly
400075846. 400085347	Problem	VC 3.95.3	VC 3.95.0	Touch screen calibration is imprecise on PP500 series devices.
400077222. 400078545	Problem	VC 3.95.2	VC 3.95.0	Error when text is loaded from a text file with only one entry
400078613	Problem	VC 3.95.2	ARSG4_4.00.22_V04.00	When running ARwin on a PP500, setting a PP500 as the terminal causes a Windows blue screen.
400061529	Problem	VC 3.95.1	V3.00.90.16	After communication with the terminal is interrupted, VA_GetTextByTextgroup returns the status 7000.
400073709	Problem	VC 3.95.1	_	If the IP address of the terminal is defined via the terminal data object or via the AR config,
-00013108	TODIETTI	v O J.8J. I	_	there is a boot error when opening the program netsg.exe

400116902, 400134321	Problem	_	IVC 3.96.2	Switching pages sometimes resulting in page fault when using VC_Saccess / VC_Srelease in several user programs
400136544	Problem	-	VC 3.96.2	Interrupted connection without a configured LifeSign data point not detected
400155457	Problem	-	VC 3.95.5	Calling VcScrSht library cyclically causing freeze of visualization application
203224	New function	_	V3.0.71.27 SP04	Terminal mode via POWERLINK

Requests and problems by product/component

X20BC0083

Firmware

ID#400071755: known problem since VC 3.73.4

Panel not reinitialized after a lost connection

If a panel on the X2X bus is being controlled by a bus controller and loses a connection, then an error occurs during the subsequent reinitialization.

1A4300.02 (1.0 Automation Studio 3.x)

VisualComponents Editor - VC4

ID#400112360 : new function since VC 3.96.1

Function for reading the limits of a data point

1A4000.02 Visual Components

Libraries

ID#400116355: solved problem, known since VC 3.95.9, solved since VC 3.96.2

GET_CONTRAST request handled in display driver

ID#400116355 : solved problem, known since VC 3.95.9, solved since VC 3.96.2

VA_GetBrightness() function implemented

ID#400115707: solved problem, known since VC 3.96.0, solved since VC 3.96.2

VC3 > VA_SetBrightness / VA_SetContrast adding the 0 character (ASCII 0x30) to the text field until the end of the line if one of the functions is called with the value 100

ID#400108187 : solved problem, known since VC 3.95.8, solved since VC 3.95.9 $\,$

 ${\bf Errorhandling\ width\ VcScrSht\ is\ important}$

If the ScreenShot() FUB of VcScrSht library returns an error and the error is not catched correctly by the user task, an Error 25062 Memory not in heap will occur.

ID#400104823 : solved problem, known since VC 3.95.6, solved since VC 3.95.9

Memory error when writing calibration data

An error in the implementation causes a memory leak when writing calibration data. This error can take up the entire memory after a certain amount of time when calling e.g. VA_SetBrightness() cyclically.

ID#400106404 : solved problem, known since VC 3.95.6, solved since VC 3.96.1

Invalid value in pv-description field

When writing the parameter, random values are applied and saved in the event.

ID#400087761 : solved problem, known since VC 3.95.5, solved since VC 3.95.8

VA_GetAlarmCount returns the wrong value for vaALS_NOTACKNOWLEDGED

ID#400078627 : solved problem, known since VC 3.95.0, solved since VC 3.95.3

Version number of VC3 modules not displayed correctly

ID#400112317 : new function since VC 3.96.1

Request > Vclib > Getting limits of a numerical input field

Request > Vclib > Getting limits of a numerical input field

SG3 Runtime

ID#400129423: solved problem, known since VC 3.96.2, solved since VC 3.96.3

Special characters not displayed on panel 4B1270.00-K36.

ID#400097156 : solved problem, known since VC 3.95.6, solved since VC 3.95.8

Key matrix resets properly after PLC restart now.

ID#400093073: solved problem, known since VC 3.95.5, solved since VC 3.95.7

24x PW35 on X2X don't work fully

ID#400071755 : solved problem, known since VC 3.73.4, solved since VC 3.95.4

Panel behind a bus controller sometimes not initialized after a power failure or a lost bus connection

SG4 - Common

ID# 400075846, 400085347 : solved problem, known since VC 3.95.0, solved since VC 3.95.3

Touch screen calibration is imprecise on PP500 series devices.

The deviation is most pronounced towards the top left and gets better as you move towards the bottom right.

SG4 Compiler

ID#400096559: new function since VC 3.95.7

An error in the configuration of the default language causes the terminal target to freeze at 100% during booting.

An error in the configuration of the default language causes the terminal target to freeze at 100% during booting. The visualization isn't started.

SG4 Runtime - Alarmsystem

ID# 400119167, 400119471, 400125693 : solved problem, known since VC 3.96.0, solved since VC 3.96.2

Corrected page fault when changing the line in the alarm list several times

ID# 400092481, 400097097 : solved problem, known since VC 3.95.6, solved since VC 3.95.7

FB BatteryInfo doesn't work for APC810.HwGetBattStatus(2) must be used.

ID# 400077803, 400092481 : solved problem, known since VC 3.95.0, solved since VC 3.95.6

FB BatteryInfo doesn't work for APC810. HwGetBatteryInfo must be used.

ID# 400065496, 400082552 : solved problem, known since VC 3.73.0, solved since VC 3.95.8

Alarms set to Acknowledge=Required, are still shown in the active alarm list even if they are already inactive.

SG4 Runtime - Common

ID#400153604 : solved problem, known since VC 3.96.3, solved since VC 3.96.4

Page change in VC 3.96.3 with AR C4.01 incredibly slow

ID#400115430 : solved problem, known since V3.00.90.30 SP0x, solved since VC 3.96.4

Guaranteed correct initialization sequence of visapi and viscomp modules VC3 handle is returned.

ID#400116902 : solved problem, known since VC 3.96.0, solved since VC 3.96.2

 $Switching\ pages\ sometimes\ resulting\ in\ page\ fault\ when\ using\ VC_Saccess\ /\ VC_Srelease\ in\ several\ user\ programs$

ID#400117729 : solved problem, known since VC 3.95.9, solved since VC 3.96.2

VC4 TargetResourceRoot > Error replacing texts (individual texts are not replaced)

ID# 400115140, 400119471 : solved problem, known since VC 3.95.8, solved since VC 3.96.1

Page fault when using VA_TextOut extensively

ID#400114025: solved problem, known since VC 3.95.8, solved since VC 3.96.1

SXGA resolution 1280 x 1024 with 32-bit color depth now supported

ID#400110961 : solved problem, known since VC 3.95.8, solved since VC 3.95.9 $\,$

Full HD resolution is scaled on the APC810 GM45 CPU when operated on an AP830 display.

ID#400110682: solved problem, known since VC 3.95.8, solved since VC 3.95.9

VA_GetTouchAction hangs at status 1 (pressed) randomly when send event is delayed.

ID#400106979 : solved problem, known since V3.00.90.24 SP0x, solved since VC 3.95.9 $\,$

 $VC4 > Switching \ to \ trend \ page \ with \ disabled \ Trend Value Scales \ (disabled \ by \ Runtime -> Status Datapoint) \ causes \ a \ page \ fault.$

ID#400103303 : solved problem, known since VC 3.95.7, solved since VC 3.95.8

Repeated downloads of visualization cause warning 28715 (unable to create Rtk object)

ID#400102814 : solved problem, known since VC 3.95.7, solved since VC 3.95.8 $\,$

Stack overflow when text snippets work with pos. or neg. infinity values for the float and double types

ID#400101767: solved problem, known since VC 3.95.7, solved since VC 3.95.9

VCresman violated protected memory after restarting an HMI application. This error occurred if notifications of DP changes for the previous HMI application were not sent. This behavior has been corrected.

ID#400101336: solved problem, known since VC 3.95.7, solved since VC 3.96.3

Rounding errors visible between time scale and value if the number of displayed values (<50) is reduced

ID#400091811: solved problem, known since VC 3.95.6, solved since VC 3.95.8

XGA resolution on an external monitor now working with APC510/511, APC620 and APC810

ID#400089532 : solved problem, known since VC 3.95.6, solved since VC 3.95.7

VC does not yet support APC51x devices

ID# 400087835, 400087699: solved problem, known since VC 3.95.5, solved since VC 3.95.6

Transfer error when VA_GetActiveAlarmCount or VA_GetAlarmCount are called in a user task

ID#400083646: solved problem, known since VC 3.95.3, solved since VC 3.95.6

Internal VC4 IP address data point not shown for X2CP1485 CPUs

ID#400082027 : solved problem, known since VC 3.95.3, solved since VC 3.95.7

Bitmap display -> Page fault at page change when VNC client is connected

ID# 400080579, 400082643 : solved problem, known since VC 3.95.0, solved since VC 3.95.7

VC_CopyMemoryToScreen only copies parts of the specified area when the display is rotated by 90° | 270°

ID# 400077222, 400078545 : solved problem, known since VC 3.95.0, solved since VC 3.95.2

Error when text is loaded from a text file with only one entry

ID#400155457: known problem since VC 3.95.5

Calling VcScrSht library cyclically causing freeze of visualization application

ID# 400116902, 400134321 : known problem since VC 3.96.2

Switching pages sometimes resulting in page fault when using VC_Saccess / VC_Srelease in several user programs

SG4 Runtime - Controls

ID#400133833: solved problem, known since VC 3.96.2, solved since VC 3.96.3

Trend > Scale > Scroll > Mode Factor, faulty time specified after scrolling

ID#400133833: solved problem, known since VC 3.96.2, solved since VC 3.96.3

VC4 > Trend > Scale > Zoom > Span mode - TimeSpanDatapoint overflow

ID#400121179 : solved problem, known since VC 3.96.1, solved since VC 3.96.3

VC4 > Trend time drifting with respect to system time

ID#400131837: solved problem, known since VC 4.05.6, solved since VC 3.96.3

Continuous user trend fluctuations with SampleRate <1 (milliseconds not taken into account on display)

ID#400128245 : solved problem, known since VC 3.96.2, solved since VC 3.96.3

Page fault if trend data (trend curve) configured multiple times in a trend

ID#400123606 : solved problem, known since VC 3.96.1, solved since VC 3.96.3

Trend > ValueScale > MinValue = 0, MaxValue = 0.6–0.9 > Values not displayed

ID# 400122618, 400122696, 400125727 : solved problem, known since VC 3.96.1, solved since VC 3.96.2

VC4 > Trend (type: Online): Relative time displayed beginning with 0 on the time axis (should be current time)

This error results from the correction of A&P 346060.

ID# 400116721, 400119206: solved problem, known since VC 3.95.9, solved since VC 3.96.1

Trend control (Type: User) shows current time on time scale axis if no SampleDateTimeDatapoint is connected.

ID#400111493 : solved problem, known since V3.00.90.25 SP0x, solved since VC 3.95.9 $\,$

Hotspot catch release event when NumPad (overlay) is closed

ID#400109716: solved problem, known since V3.00.90.24 SP0x, solved since VC 3.95.9

VC4 > EditControl "Delete" command on the first line causes a page fault

ID#400107408 : solved problem, known since V3.00.90.24 SP0x, solved since VC 3.95.9 $\,$

With the password control, the "HasFocus" flag is set in the status register although the control has been hidden with the "Hide" bit.

ID#400107392 : solved problem, known since V3.00.90.24 SP0x, solved since VC 3.95.9

VC4 > Alarm > WrapMode Endless causes PageFault after scrolling and ack one alarm

ID#400105632 : solved problem, known since V3.00.90.24 SP0x, solved since VC 3.95.8

Errors in trend display if two or more independent trends are configured on one time scale

ID#400101146: solved problem, known since VC 3.95.6, solved since VC 3.95.8

If a DP is connected to several user trends, they are not displayed correctly.

ID#400100072: solved problem, known since VC 3.95.7, solved since VC 3.95.8

Error when setting the Numeric control to "Hide" with the touchpad during input

ID#400097367: solved problem, known since VC 3.95.6, solved since VC 3.95.7

Changing pages while saving causes a "deadlock" (visualization freezes).

ID# 400087974, 400050060, 400028969 : solved problem, known since VC 3.95.5, solved since VC 3.96.3

Overflow when synchronizing the trend with the system clock if Sample Rate > 32535

ID#400094505: solved problem, known since VC 3.95.6, solved since VC 3.95.7

Trend grid background shown even though layer is hidden using status data point

ID#400085328: solved problem, known since VC 3.95.5, solved since VC 3.95.7

Trend -> CursorTime data points on the TrendTime scale are not scaled.

ID# 400087974, 400050060, 400124149, 400125253 : solved problem, known since VC 3.95.5, solved since VC 3.96.3

Overflow when synchronizing the trend with the system clock if Sample Rate > 32535

ID#400082207: solved problem, known since VC 3.35.4, solved since VC 3.95.5

Date/Time display in the Alarm control doesn't release internal memory for empty format string.

ID# 400081836, 400083464 : solved problem, known since VC 3.95.3, solved since VC 3.96.3

Trend updated too often and CPU load at 100% when setting AutomaticScrollOffset to 0

ID#400079372: solved problem, known since VC 3.95.0, solved since VC 3.95.7

When the "insert" command is used to insert a text at the end, subsequent input in the Edit control is faulty.

ID# 400078084, 400091350, 400139741 : solved problem, known since VC 3.95.0, solved since VC 3.96.3

Value change in user trend data causing reset of zoom settings

ID#400078529 : solved problem, known since VC 3.95.0, solved since VC 3.95.4 $\,$

Error in repaint

In some cases, the time axis is not redrawn

ID#400079295: solved problem, known since VC 3.95.0, solved since VC 3.95.4

When the IPAddress data point is written cyclically, the touch pad keeps closing

When the IPAddress data point is written cyclically, the page is refreshed every time (like when switching languages). In the process, all touch pads (overlays) are closed.

Workaround: Only write the IPAddress data point when its value has changed.

ID#400077340 : solved problem, known since VC 3.95.0, solved since VC 3.95.6

With a very small string control (ControlWidth < CharWidth) and TextLengthOverrun Cut = True the program runs in an endless loop (100% usage)

ID#400076230: solved problem, known since VC 3.95.0, solved since VC 3.95.4

Incorrect display in DropDown control

ID#400124119 : new function since VC 3.96.3

Trend > ValueScale > MaxValue= 9-6, unnecessary decimal places (since always zero) displayed

SG4 Runtime - Keyhandling

ID#400125616: solved problem, known since V3.00.90.27 SP0x, solved since VC 3.96.3

Possible to trigger any key functions when using extension keys with handwheel (using the handwheel), such as the 5AC800.EXT1-K02

ID#400094705 : solved problem, known since V3.00.90.22 SP0x, solved since VC 3.95.7

APC51x not supported by VC

SG4 Runtime - TerminalMode

ID#400109703 : solved problem, known since VC 3.95.8, solved since VC 3.95.9

Exception when switching from terminal to administrator mode if ARwin is selected in the VC Windows terminal but no boot loader is configured

ID#400106379: solved problem, known since VC 3.95.6, solved since VC 3.95.9

Bitmap with FillArea at position Left=-1 and Top=-1 causes PF (this faulty configuration can occur when replacing bitmaps).

ID#400102666; solved problem, known since VC 3.95.7, solved since VC 3.95.8

Selecting the rotated image has been corrected.

ID# 400088591, 400089914 : solved problem, known since VC 3.95.5, solved since VC 3.95.7

Considerable performance increase with VC optimization // Difference between WinXP and Win7 is only subjective

ID#400086001: solved problem, known since VC 3.95.3, solved since VC 3.95.7

Page fault when the VA_SetBrightness function is called on a VCWT

ID#400083974: solved problem, known since VC 3.95.4, solved since VC 3.95.5

Error saving the brightness/contrast settings in the file VcData if there is no touch screen calibration data.

When the brightness/contrast are changed, the new setting is saved in the file VcData. With an embedded target, this file also contains the touch screen calibration data. For a VCWT there is no touch screen calibration data (calibration is performed in Windows), an error occurs when saving the touch calibration data.

ID#400083204: solved problem, known since VC 3.95.3, solved since VC 3.95.6

Error in VA AlGetCurPos on the terminal when changing the page

ID#400075434: solved problem, known since VC 3.95.3, solved since VC 3.95.4

VC ProjectLoader freezes or crashes when a visualization application is loaded

ID#400082098 : solved problem, known since VC 3.95.3, solved since VC 3.95.5

VC Windows Terminal: Unhandled exception after reinstall

If the VC Windows terminal packet is uninstalled and reinstalled in a different directory, an exception is thrown in the VC target configurator when you switch to the "Log" tab.

ID#400080360: solved problem, known since VC 3.95.3, solved since VC 3.95.4

Loading BR modules to the terminal freezes (progress bar stops at x%) or the loaded BR modules are defective

ID#400078613 : solved problem, known since ARSG4_4.00.22_V04.00, solved since VC 3.95.2

When running ARwin on a PP500, setting a PP500 as the terminal causes a Windows blue screen.

ID#400061529 : solved problem, known since V3.00.90.16, solved since VC 3.95.1

After communication with the terminal is interrupted, VA_GetTextByTextgroup returns the status 7000.

ID#400073709 : solved problem, known since , solved since VC 3.95.1 $\,$

If the IP address of the terminal is defined via the terminal data object or via the AR config, there is a boot error when opening the program netsq.exe

ID#203224 :

Terminal mode via POWERLINK

ID#400136544: known problem since VC 3.96.2

Interrupted connection without a configured LifeSign data point not detected

SG4 Runtime - VNC

ID#400118912: solved problem, known since VC 3.96.0, solved since VC 3.96.2

System pushed to the limit with VNC visualization with large trend, small sample rate and 32-bit color depth

ID#400082576: solved problem, known since VC 3.95.3, solved since VC 3.96.1

Status of LEDs on the MP50 not updated on lost connection

ID# 400081712 : solved problem, known since ARSG4_4.00.16_P04.00, solved since VC 3.95.6 $\,$

Problems with ARwin in Windows 7 when firewall is on

In order to avoid ARwin communication problems in Windows 7, the Windows Firewall must be disabled for the "Realtime OS Virtual Network interface.