momentum

Property Risk Assessment

Report Date: 10/04/2025

Property Details

27 Leeuwen St, Cape Town City Centre, 8001

Property Type: Apartment

Size: 85 m²

Bedrooms: 2

Bathrooms: 2

Parking: 1

Condition: Excellent

Risk Assessment

Overall Risk Score

58%

Moderate Risk

Risk Breakdown

Security	21/50 (42%)
Environmental	21/40 (53%)
Flood	10/10 (100%)
Climate	66/270 (24%)
Hail	10/30 (33%)

Building Details

Structure Information

Roof Type:	concrete
Wall Material:	brick
Non-Standard Structure:	no
Residence Type:	main
Commune:	no
Plot or Farm:	no

Safety Features

Fire Retardant:	yes
Lightning Conductor:	no
Surge Arrester:	yes
Nearby Water Bodies:	no

Geyser Information

Electric	Gas	Heat Pump	Solar Water
1	0	0	0

Security Details

Perimeter Protection

Perimeter Wall Type:	brick wall higher than 1.8m
Electric Fence:	no
Controlled Access:	yes

Building Protection

Burglar Bars:	yes
Security Gates:	yes
Radio-Linked Alarm:	yes
Security Guard:	yes

Neighborhood Demographics

Population Demographics

Dominant Age Group:	25-35 years
Dominant Race:	Mixed
Gender Ratio:	Balanced (52% female)

Economic Indicators

Income Classification:	Upper Middle
Average Building Value:	R3,850,000
National Living Index (NLI):	7/10

Detailed Risk Factors

Security Risk Medium

Score: 21 points | Maximum: 50 points | Percentage: 42%

Dimension	Outcome	Risk Factor
Inside security area:	Yes	1 point
Next to open areas:	Yes	10 points
Distance to industrial:	1.8km	5 points
Distance to informal settlements:	3.2km	5 points
Construction in the area:	No	0 points
Total		21 points

Environmental Risk Medium

Score: 21 points	Maximum: 40 points	Percentage: 53%

- Moderate air pollution from nearby traffic
- Some noise pollution during peak hours
- Limited exposure to industrial contaminants
- Property is in an area with high fire risk rating
- Roof top solar installation increases potential fire hazard

Dimension	Outcome	Risk Factor
Fire risk:	High	10 points
Roof top solar (fire risk):	Yes	10 points
Distance to water:	>100m (225m)	0 points
Slope:	5°	1 point
Total		21 points

Flood Risk High

Score: 10 points	Maximum: 10 points	Percentage: 100%

- Property is located in a 1-in-100 year flood zone
- Historical flooding has occurred in this area
- Limited drainage infrastructure in surrounding streets
- Basement level is particularly vulnerable to water ingress

Dimension	Outcome	Risk Factor
Flood Risk	High	10 points
Total		10 points

Climate Risk Low

Score: 66 points	Maximum: 270 points	Percentage: 24%

- Property is not in a high-risk zone for sea level rise
- Building materials are resistant to temperature fluctuations
- Energy-efficient design helps mitigate extreme weather impacts
- Property has good natural ventilation reducing AC dependency

Category	Dimension	Outcome	Risk Factor
Temperature Related	Changing of air temperature	Medium risk	5 points
Temperature Related	Heat Stress	Low risk	2 points
Temperature Related	Temperature variability	Medium risk	5 points
Temperature Related	Heat wave	Medium risk	5 points
Temperature Related	Wildfire	High Risk	10 points
Wind related	Changing wind patterns	Low risk	2 points
Total (all climate factors)			66 points

Note: Showing 6 of 12 climate risk factors

Hail Risk Medium

Score: 10 points Maximum: 30 points **Percentage: 33%**

- Roof may require inspection to assess hail resistance
- Partial covered parking for vehicles
- Standard roofing materials with moderate resistance to hail impact

Dimension	Outcome	Risk Factor
Roof condition	Fair/Good - Moderate impact resistance	4 points
Hail frequency in area	Medium - 1-2 events per year	5 points
Vehicle protection	Partial covered parking available	2 points
Roof material	Standard materials in good condition	3 points
Proximity to high-risk zone	Within 5km of high frequency area	2 points
Total		10 points

Insurance-Relevant Metrics:

Max Hail Size: **20-40mm**

Annual Frequency: **3 events/year**

Damage Probability: **45%**

Roof Vulnerability: **Low**

Return Period: **1 in 3 years**

Insurance Recommendations

- Consider upgrading security systems and access control.
- Install additional exterior lighting around the property.
- Obtain comprehensive flood insurance coverage.
- Install flood barriers and improved drainage systems.
- Consider roof reinforcement to withstand maximum hail size of 20-40mm.
- Obtain specialized hail insurance coverage with an annual damage probability of 45%.
- Plan for 3 potential hail events per year with a return period of 1 in 3 years.
- Conduct a professional property inspection before finalizing insurance coverage.
- Consider bundling multiple insurance policies for better protection and rates.

Risk Summary

This property presents an overall moderate risk profile (58%), with most risk factors being well-managed or naturally low. However, there are specific areas of concern:

- **High Flood Risk:** The property's location in a flood-prone area represents the most significant risk factor and should be carefully considered.
- **Medium Security Risk:** While not critical, security measures could be improved to enhance property protection.
- **Medium Environmental & Hail Risk:** These moderate risk factors should be monitored but don't present immediate concerns.
- **Low Climate Risk:** The property is well-positioned to withstand long-term climate change impacts.