Supplier Review Package

Worksurface DWG check • Lock position • Edgebanding changes

From: Supplier request to Wes
Reviewed by: _____ **Date:** _____
Return to: Supplier (reply with completed decisions on pages 1–4)

Heads up before you start: (1) The drawing for **5CWS-M2460-W** is believed to be wrong. The supplier needs a correct original from you. (2) The supplier's email refers to a lock system "below", but no picture or part number came through. Ask them to resend it. (3) Pack quantity is **1 pc/pack** for Groups A–C but **2 pcs/pack** for Groups D and E. Confirm that is intended. (4) **Group E drawings (5 of 5) received and checked.** One issue: **5CWS-M2448-WHV2** has a 224 mm cutout, not 389 mm. Details in Part 1. The other 18 drawings have not been received yet.

Part 1 — Worksurface DWG Review (23 drawings)

For each drawing, check the four items against the attached DWG: hole positions, model number, size, packing. Mark Notes with anything off.

Drawing / Model No.	Hole pos.	Model No.	Size	Pack	Notes
GROUP A — 4 pilot holes (one at each corner), 3 different colors with 3 different sizes, 1 pc per pack					
5CLWS2460	☐	☐	☐	☐	
5CLWS2472	☐	☐	☐	☐	
5CLWS3060	☐	☐	☐	☐	
Check: each of the 3 models has its own color and its own size (no duplicates).					
GROUP B — 4 pilot holes (one at each corner), circular grommet, 1 pc per pack					
5QWMU2442G2	☐	☐	☐	☐	
5QWMU2448G2	☐	☐	☐	☐	
5QWMU2460G2	☐	☐	☐	☐	
5QWMU2472G2	☐	☐	☐	☐	
5QWMU3060G2	☐	☐	☐	☐	
5QWMU3072G2	☐	☐	☐	☐	
GROUP C — 12 pcs M6 inserts, 2 pilot holes, 1 square cable grommet at 290 mm length, 1 pc per pack					
5CWS2448W12	☐	☐	☐	☐	
5CWS2460W12	☐	☐	☐	☐	
5CWS2472W12	☐	☐	☐	☐	
5CWS3048W12	☐	☐	☐	☐	
5CWS3060W12	☐	☐	☐	☐	
5CWS3072W12	☐	☐	☐	☐	
GROUP D — same function as Group C, square cable grommet at 224 mm length, 2 pcs per pack					
5CWS-M2448-W	☐	☐	☐	☐	
5CWS-M2460-W Supplier believes this drawing is WRONG. They received the wrong original. Send the correct one.	☐	☐	☐	☐	
5CWS-M3048-W	☐	☐	☐	☐	
GROUP E — square cable grommet cutout at 389 mm, 12 M6 inserts, 2 pilot holes, 2 pcs per pack **Pre-checked against the 5 drawings you sent. ✓ = matches the email, ! = needs your attention. Please verify.**					

5CWS-M2448-WHV2	☑	☑	!	☑	**Cutout is 224 mm, not 389.** Cutout height is 104 (others 106.5). Notes list is missing "white" board and the "junction box not included" line.
5CWS-M2460-WHV2	☑	☑	☑	☑	1524 × 609. Cutout 389 × 106.5, centered (567.5 each side).
5CWS-M2472-WHV2	☑	☑	☑	☑	1829 × 609. Cutout 389 × 106.5, centered (720 each side).
5CWS-M3060-WHV2	☑	☑	☑	☑	1524 × 762. Cutout 389 × 106.5, centered (567.5 each side).
5CWS-M3072-WHV2	☑	☑	☑	☑	1829 × 762. Cutout 389 × 106.5, centered (720 each side).
Common to all five: 12 × Ø8 deep 20 / Ø13 × 90° (6 holes each end; rows 146 mm from the top edge and 321 mm apart; hole pitch 28 mm, 31 mm from the left edge; 142 mm bottom margin on 609 depth, 295 mm on 762). 2 × Ø3 deep 3 pilot holes (one dimensioned: 197 mm from the left, 64.5 mm down). Cutout 38 mm from the top edge, R6 corners. 25 mm melamine board, 3 mm same-color edgebanding, 2 pcs per pack, US packing.					

Part 1 questions to answer back

1a. 5CWS-M2460-W: the drawing is wrong. Can you send the correct original, or confirm which drawing is the right one?

1b. Group D: is it also 12 M6 inserts and 2 pilot holes (like Group C)? The email only says "same function". (Group E drawings confirm 12 inserts and 2 pilot holes.)

1c. Packing: Groups A–C are 1 pc per pack and Groups D–E are 2 pcs per pack. Is the difference intended?

1d. 5CWS-M2448-WHV2: the drawing shows a **224 mm** cutout (104 mm tall), but Group E is supposed to be 389 mm (106.5 mm tall) and 224 mm is the Group D size. Is this the wrong drawing, or is the 24x48 intentionally different? Also, its notes omit "white" board and "junction box not included". Confirm which is correct.

1e. All five Group E drawings: only one Ø3 pilot hole is dimensioned (197 mm from the left, 64.5 mm down). The second one (a dot near the top right) has no dimension. Confirm it mirrors the first. Also, the drawings call out Ø8 deep 20 / Ø13 × 90° but never name the M6 insert. Confirm the insert part.

1f. Edgebanding: the Group E drawings already say 3 mm same-color edgebanding. Is that the same change you want in items 3 to 5?

Part 2 — Decisions Needed (4 items)

2. Storage Cabinet lock position

Drawing refs: **SC** drawing (Storage Cabinet) and **LF** drawing (for lock position comparison). Lock system image/part no. from the supplier: **not received**.

- Supplier will use the lock system pictured in their email for the Storage Cabinet.
- Its lock position is **9.5 mm lower** than the LF.

Question: Will you accept the 9.5 mm lower lock position?

☐ Accept ☐ Reject ☐ Accept with changes ☐ Need the lock picture / part no. first

3. Desk Shells — edgebanding

Drawing refs: desk shell drawings (all models). Note: matches your meeting note "Desk shell – Edge, 3mm".

- **3a.** End panel edgebanding: change from **2 mm to 3 mm**.
- **3b.** Modesty panel upper edge (not visible): change from **2 mm to 1 mm** and match the board color.

3a: ☐ Accept ☐ Reject ☐ Other: _____

3b: ☐ Accept ☐ Reject ☐ Other: _____

4. Credenza, Return, Bridge, etc. — upper edgebanding

Drawing refs: Credenza, Return and Bridge drawings. The supplier's "etc." means you should ask which other models are included.

- Change the upper edgebanding from **2 mm to 3 mm**.

☐ Accept ☐ Reject ☐ Other: _____

Ask: which other models does "etc." cover?

5. Bookcase — edgebanding

Drawing refs: Bookcase drawings. Note: the same bookcase also has your pending "notch in shelf for pin" item.

- **5a.** Upper edgebanding: change from **2 mm to 3 mm**.
- **5b.** Back panel upper edgebanding: change from **2 mm to 1 mm**.

5a: ☐ Accept ☐ Reject ☐ Other: _____

5b: ☐ Accept ☐ Reject ☐ Other: _____

Reply to Supplier

Summary / anything else to send back

Sign-off: _____ Date: _____