

# Daily Fault & Alarm Log - May 1, 2026

Document Code: FAL-NOC-20260501

Shift Summary prepared by: Adaeze Nwosu and Oluwaseun Adeyemi

Reviewed by: Amaka Obi

## 1. Day Summary Stats

- Total Alarms: 34
- Actionable: 9
- Auto-Cleared: 25
- P1: 0
- P2: 3
- P3: 6

## 2. Full Alarm Log

| Time  | Tower         | Alarm Type            | Severity | Duration | Action                                   | Resolved By      |
|-------|---------------|-----------------------|----------|----------|------------------------------------------|------------------|
| 09:14 | TWR-OJO-002   | High Load Threshold   | WARN     | ongoing  | Manual check, load-shed triggered        | oluwaseun.a      |
| 10:02 | TWR-AGE-009   | Rectifier Voltage Dip | INFO     | 5 min    | Auto-cleared                             | System           |
| 11:30 | TWR-LAG-W-031 | High Temperature      | WARN     | 12 min   | Cooling fan fault, technician dispatched | Fedma Aliyu      |
| 12:20 | TWR-IKJ-019   | Transmission Error    | P2       | 18 min   | Fiber reroute applied                    | Ibrahim Musa     |
| 13:45 | TWR-LEK-003   | Link Degradation      | INFO     | 3 min    | Auto-cleared, weather related            | System           |
| 14:10 | TWR-VI-005    | Security Sensor Fault | P3       | 7 min    | Reset remotely                           | Tunde Balogun    |
| 15:00 | TWR-LAG-W-022 | Jitter Elevated       | WARN     | ongoing  | Microwave alignment check scheduled      | Ibrahim Musa     |
| 16:25 | TWR-APP-004   | Generator Low Fuel    | P2       | 25 min   | Refueling initiated                      | Babatunde Okafor |
| 17:05 | TWR-IKO-011   | Cooling Unit Alert    | INFO     | 4 min    | Auto-cleared                             | System           |
| 18:35 | TWR-OJO-002   | Load Critical         | WARN     | 22 min   | Load-shed to TWR-OJO-005                 | System           |
| 19:02 | TWR-OJO-002   | High Load Threshold   | WARN     | 15 min   | Manual load balancing                    | oluwaseun.a      |
| 19:41 | TWR-OJO-002   | Load Critical         | WARN     | 19 min   | Load-shed applied                        | System           |
| 20:15 | TWR-OJO-002   | High Load Threshold   | WARN     | ongoing  | Manual check                             | oluwaseun.a      |

## 3. Recurring Alarm Pattern Noted

TWR-OJO-002 triggered load alarms 4 times today (18:35, 19:02, 19:41, 20:15). All were related to evening peak traffic congestion.

## 4. Outstanding Alarms at Day End

- INC-2838: Festac congestion (OJO-002) - still active.
- INC-2836: Microwave jitter (LAG-W-022) - still active.

## **5. Alarm Noise Ratio**

25 auto-cleared alarms were not actionable. Threshold tuning will be discussed in the next team meeting to reduce noise.

## **6. Sign-off**

Prepared by:

Adaeze Nwosu - Senior NOC Analyst

Oluwaseun Adeyemi - NOC Engineer

Reviewed by:

Amaka Obi - NOC Manager

Date: May 1, 2026