





Individual Phase Windings

*NOTE: Positive winding is clockwise & negative winding is anti-clockwise



3 Phase Connection + neutral Tap

*NOTE: P1 is Molex mf3 socket connector
*NOTE: T1 is the neutral central tap for testing



TITLE: Armature WYE winding		REV: 1.0
OpenLSM	Company: N/A	Sheet: 1/1
	Date: 2026-01-17 Drawn By: wgbowley	