Normality QC: differences between the methods

Points near the line support normality; mild, judged deviation is usually acceptable.