Normality QC: paired differences

Points near the line support normality; mild, judged deviation is usually acceptable.