Normality QC: values of each group

Points near the line support normality; mild, judged deviation is usually acceptable.