Normality QC: group values of each feature

Points near the line support normality; mild, judged deviation is usually acceptable.