## Normality QC: variable values

Points near the line support normality; mild, judged deviation is usually acceptable.