

FINAL INSPECTION REPORT

EXTERNAL / INTERNAL REPAIR & WARRANTY

 No
 :
 Unit No
 :
 RD3021

 Wo No.
 :
 6887356
 Unit Model
 :
 Cat 789C

Component Desc : GREASE INJECTOR Repair By : BSF Machine Rebuilt Workshop

Part No : 01-085771PXB Qoute No :

Job No : DN No : 043773

No	Description		Check List
1	Ensure the Final Inspection Report from TCI Workshop (TCI-PLT-FO-166) is available		
2	Ensure the detail component is allign with information from JDE (WO, P/N,OP)		
3	Ensure BSF Logistic Tag is available		
4	Visual Inspection		
	a. All bolts properly secured and fitted		
	b. Stand is proper && safe (no damage found on stand)		
	c. Check cleanliness condition (no oil spill found)		
	d. Check the cover condition is properly secured for component protection		
5	Take a pictures		
	a. Vendor ID Stamp or ID Plate		
	b. Overall view of component		
	c. Ensure all pictures have been downloaded to BSF-PER server and rename the file name to each WO		
6	Ensure testing report is attached on component, record it by taking picture (for major component only, i.e. : engine, transmission, torque converter, bevel gear, final drive and all hyd. cylinders)		: 🗆
7	Sign then record this report after finished inspection		
Remarks / Findings			
	cted will be put "ON HOLD" sticker for further action taken		
Issued By, QA/QC Engineer Acknowledged By, Supervisor/Superinter		wledged By, visor/Superintend/Manager	
Signature : tral	nayu Date: Signatu	rre: Lutfi syafiq Date:	

08/01/2024 TCI - PLT - FO- 186