




This is the pinout for a custom female DB25 cable. This board requires a custom cable to connect to its sensors. Use this guide when making a new cable. Cable RX goes to Board TX, same for TX to RX.

Make sure to check all connections prior to connecting to power.

Incorrect wiring can cause permanent damage to sensors and/or board.

Use a multimeter set to continuity mode to ensure connections. Have a team member verify when finished.

Print this page out and have an installer sign here to verify connections:

Sheet: /
File: sensor_pinout.kicad_sch

Title: DB25 Pinout

Size: A4 Date:

KiCad E.D.A. 10.0.1

Rev:
Id: 8/8