

WIRING DIAGRAMS



PROTECTION TECHNOLOGY
MADE SIMPLE

 $MRMV4 \mid \ {\tt Motor \ Protection}$


Version: 3.7

Original document

English


This document does not replace the Technical Manual.

MRMV4-2A0AAA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0AAB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0ABA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0ABB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0ACA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- **X102** Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0ACB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0ADA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, Fiber optics interface, ST Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0ADB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, Fiber optics interface, ST Connector
- **X104** IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0AEA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0AEB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0AFA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, Fiber optics interface, ST Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0AFB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, Fiber optics interface, ST Connector
- **X104** IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0AGA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0AGB




- + Conformal Coating (for installations in harsh environment)
- **X1** DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0AHA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0AHB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- **X104** IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0AIA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- **X104** IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0AIB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0AKA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0AKB




- + Conformal Coating (for installations in harsh environment)
- **X1** DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0ALA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0ALB




- + Conformal Coating (for installations in harsh environment)
- **X1** DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0ATA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- **X104** IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0ATB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0BAA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0BAB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0BBA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0BBB




- + Conformal Coating (for installations in harsh environment)
- **X1** DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0BCA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0BCB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0BDA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, Fiber optics interface, ST Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0BDB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, Fiber optics interface, ST Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0BEA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0BEB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0BFA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, Fiber optics interface, ST Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0BFB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, Fiber optics interface, ST Connector
- **X104** IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0BGA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0BGB




- + Conformal Coating (for installations in harsh environment)
- **X1** DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0BHA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0BHB




- + Conformal Coating (for installations in harsh environment)
- **X1** DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0BIA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0BIB




- + Conformal Coating (for installations in harsh environment)
- **X1** DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0BKA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0BKB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0BLA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0BLB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0BTA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A0BTB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1AAA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1AAB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1ABA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1ABB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1ACA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 Tls: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1ACB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1ADA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, Fiber optics interface, ST Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1ADB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, Fiber optics interface, ST Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1AEA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1AEB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, RS485, D-SUB
- **X104** IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1AFA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, Fiber optics interface, ST Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1AFB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, Fiber optics interface, ST Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1AGA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1AGB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1AHA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 Tls: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1AHB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 Tls: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1AIA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1AIB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1AKA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1AKB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1ALA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1ALB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1ATA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- **X104** IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1ATB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1BAA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1BAB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1BBA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1BBB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1BCA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1BCB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1BDA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, Fiber optics interface, ST Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1BDB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, Fiber optics interface, ST Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1BEA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1BEB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1BFA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, Fiber optics interface, ST Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1BFB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, Fiber optics interface, ST Connector
- **X104** IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1BGA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1BGB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1BHA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1BHB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 Tls: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1BIA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- **X104** IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1BIB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1BKA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1BKB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- **X104** IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1BLA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1BLB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1BTA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2A1BTB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0AAA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0AAB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0ABA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0ABB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0ACA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0ACB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0ADA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, Fiber optics interface, ST Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0ADB




- + Conformal Coating (for installations in harsh environment)
- **X1** DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, Fiber optics interface, ST Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0AEA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0AEB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0AFA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, Fiber optics interface, ST Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0AFB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, Fiber optics interface, ST Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0AGA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0AGB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0AHA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0AHB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0AIA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0AIB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0AKA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0AKB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0ALA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0ALB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0ATA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0ATB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0BAA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0BAB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0BBA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0BBB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0BCA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0BCB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0BDA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, Fiber optics interface, ST Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0BDB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, Fiber optics interface, ST Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0BEA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0BEB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0BFA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, Fiber optics interface, ST Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0BFB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, Fiber optics interface, ST Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0BGA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0BGB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0BHA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0BHB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0BIA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0BIB




- + Conformal Coating (for installations in harsh environment)
- **X1** DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0BKA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0BKB




- + Conformal Coating (for installations in harsh environment)
- **X1** DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0BLA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0BLB




- + Conformal Coating (for installations in harsh environment)
- **X1** DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0BTA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C0BTB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- **X3** TI: Standard current measuring card
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1AAA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1AAB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1ABA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1ABB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1ACA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1ACB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1ADA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, Fiber optics interface, ST Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1ADB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 Tls: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, Fiber optics interface, ST Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1AEA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1AEB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 Tls: Standard phase current measuring card and sensitive ground current measuring
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1AFA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, Fiber optics interface, ST Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1AFB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 Tls: Standard phase current measuring card and sensitive ground current measuring
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, Fiber optics interface, ST Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1AGA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1AGB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 Tls: Standard phase current measuring card and sensitive ground current measuring
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1AHA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1AHB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1AIA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1AIB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1AKA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1AKB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 Tls: Standard phase current measuring card and sensitive ground current measuring
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1ALA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1ALB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1ATA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1ATB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1BAA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 Tls: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1BAB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1BBA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1BBB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1BCA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1BCB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1BDA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, Fiber optics interface, ST Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1BDB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 Tls: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, Fiber optics interface, ST Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1BEA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1BEB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Profibus-DP, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1BFA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 Tls: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, Fiber optics interface, ST Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1BFB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 Tls: Standard phase current measuring card and sensitive ground current measuring
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, Fiber optics interface, ST Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1BGA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1BGB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, D-SUB
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1BHA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1BHB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1BIA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 Tls: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1BIB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- X4 TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1BKA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1BKB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1BLA




- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 Tls: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1BLB




- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 Tls: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1BTA



- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

MRMV4-2C1BTB



- + Conformal Coating (for installations in harsh environment)
- X1 DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- **X2** OR6: Assembly Group with 6 Output Relays
- X3 TIs: Standard phase current measuring card and sensitive ground current measuring
- **X4** TU: Card with 4 voltage transformer measuring inputs
- **X5** AnO4: Analog Outputs
- **X6** OR6: Assembly Group with 6 Output Relays
- X100 IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X102 Universal Resistance-Temperature Detector (URTD) input, Fiber optics interface, Versatile Link
- X103 IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals
- X104 IRIG-B00X, incl. System Contact (Supervision Contact)

Appendix - Legend

In this legend designations of various device types are listed, e.g. transformer protection, motor protection, generator protection, etc. Therefore it can occur that not every designation actually appears on the wiring diagram of your device.

FE — Connection of functional earth (see chapter Grounding in the Technical Manual).

Power Supply – Connection for auxiliary power supply.

IL1 - Phase current input L1 (in some countries designated as IA).
 IL2 - Phase current input L2 (in some countries designated as IB).
 IL3 - Phase current input L3 (in some countries designated as IC).

IG – Earth current input.

IL1 W1 ... IL3 W1 — Phase current input L1...L3, winding side 1.

- Phase current input L1...L3, winding side 2.

- Phase current input L1...L3, winding side 2.

- Earth current input, winding side 1 / 2.

VX — 4th voltage measuring input for measuring residual voltage or synchro-check.

BO – Binary output relay.

NO / NC — Contact output, normally open (Form A) / closed (Form B).

DI – Digital input.

COM - Common connection of digital inputs.

Out+, AnOut - Analog output + (0/4...20 mA or 0...10 V).

In-, AnIn - Analog input + (0/4...20 mA or 0...10 V).

n.c. – Not connected.

DO NOT USE – Do not use. (Caution: Non-usable internal wiring may exist.)

SC – Self-supervision contact.

HF SHIELD – Connection cable shield.

Fiber Optics / LWL – Fiber optic connection.



High PROTEG

www.SEGelectronics.de



SEG Electronics GmbH reserves the right to update any portion of this publication at any time. Information provided by SEG Electronics GmbH is believed to be correct and reliable. However, SEG Electronics GmbH assumes no responsibility unless otherwise expressly undertaken.



SEG Electronics GmbH Krefelder Weg 47 \cdot D–47906 Kempen (Germany) Postfach 10 07 55 (P.O.Box) \cdot D–47884 Kempen (Germany) Telephone: +49 (0) 21 52 145 1

Internet: www.segelectronics.de

Sales

Telephone: +49 (0) 21 52 145 331 Fax: +49 (0) 21 52 145 354 Email: SalesPGD_EMEA@woodward.com

Service

Telephone: +49 (0) 21 52 145 600 Fax: +49 (0) 21 52 145 354 Email: industrial.support@woodward.com

SEG Electronics GmbH has company-owned plants, subsidiaries, and branches, as well as authorized distributors and other authorized service and sales facilities throughout the world.

Complete address / phone / fax / email information for all locations is available on our website.