

Smallest increment for X-axis:

200 pul/rev $\xrightarrow{\text{set by DM566}}$ 1 rev = 200 pulses

SFU1204 lead (linear distance the ball nut travels)
ball screw 00

1 rev = 4mm $\rightarrow$ 200 pul yields 4mm

1 step yields 0.02m

Smallest increment for y-axis:

Same as x-axis, 1 step yields 0.02m

Smallest increment for z-axis:

200 pul/rev set by DM566 Driver

$\rightarrow$ 1 rev = 200 pulses; uses a

SFU1605 lead " 200 pul yields 5mm travel

1 step yields 0.025m