LA-UR-14-21489

Approved for public release; distribution is unlimited.

Title: Module 4 - Part 1 - Hand Calculation Methods

Author(s): Mitchell, Mark V.

Intended for: NCSP Hands-On Training

Issued: 2014-03-06



Disclaimer:

Disclaimer:
Los Alamos National Laboratory, an affirmative action/equal opportunity employer,is operated by the Los Alamos National
Security, LLC for the National NuclearSecurity Administration of the U.S. Department of Energy under contract DE-AC52-06NA25396.
By approving this article, the publisher recognizes that the U.S. Government retains nonexclusive, royalty-free license to publish or reproduce the published form of this contribution, or to allow others to do so, for U.S. Government purposes.
Los Alamos National Laboratory requests that the publisher identify this article as work performed under the auspices of the U.S. Departmentof Energy. Los Alamos National Laboratory strongly supports academic freedom and a researcher's right to publish; as an institution, however, the Laboratory does not endorse the viewpoint of a publication or guarantee its technical correctness.



Module 4 – Part 1 Hand Calculation Methods

Section 1 – Hand Calculations Introduction

Presented by: Mark Mitchell



Hand Calculation Methods

Learning Objectives

- Familiarization with common hand calculation methods
 - Single Unit Methods
 - Multiplication factor vs. fraction critical
 - Core density conversions
 - Shape conversions (Buckling conversions)
 - Array Methods
 - Limiting surface density, NB_{N²}, method
 - Surface density method
 - Density analog method
 - Solid angle method



Background

- Widely used before the existence (availability) of highspeed, large-memory, computers
- May seem obsolete today, but ...
 - Useful as a starting point for more elaborate calculations
 - Can provide insight into a problem not apparent in a computer printout
 - Can provide a "sanity check"



Other Hand Calculation Methods

- Methods discussed are not exhaustive list
- Other hand calculation methods exist
 - One-group and modified one-group diffusion theory
 - Clark's Albedo Method
 - Equilateral Hyperbola Model
 - Trombay Criticality Formula
 - Etc.



Resources

- LA-3366 (Rev), Criticality Control in Operations with Fissionable Material
- LA-10860-MS, Critical Dimensions of Systems Containing ²³⁵U. ²³⁹Pu, and ²³³U (1986 Revision)
- LA-14244-M, Hand Calculation Methods for Criticality Safety – A Primer
- NCSET Module 8, Hand Calculations Part 1
- TID-7016 (Revision 2), Nuclear Safety Guide
- Website: http://ncsc.llnl.gov/ncspMain.html



Module 4 – Part 1 Hand Calculation Methods

Section 2 – Single Unit Methods

Presented by: Mark Mitchell



Single Unit Methods

- Multiplication factor vs. fraction critical
 - Fraction critical, f
 - Relationship between k_{eff} and fraction critical
- Core density conversions
 - Convert a known critical core with a density into an equivalent critical core having another density
- Shape conversions (Buckling conversions)
 - Convert a known critical shape to another critical shape consisting of the same material



 The fraction critical may be used to determine the approximate multiplication factor

- Fraction critical
 - Defined as the ratio of the mass to the critical mass of the same material conditions, m/m_c



- For instance, the critical mass of a bare sphere of α -phase ²³⁹Pu metal is ~10,000 g
 - A bare sphere consisting of 4,500 g of α -phase ²³⁹Pu metal has a fraction critical of:

$$- f_{bare} = 4,500 g/10,000 g = 0.45$$



- The critical mass of a water-reflected sphere of α -phase ²³⁹Pu metal is ~5,400 g
 - A water-reflected sphere consisting of 4,500 g of α -phase ²³⁹Pu metal has a fraction critical of:

$$- f_{refl} = 4,500 g/5,400 g = 0.83$$



• The following figures show the k_{eff} 's as a function of the fraction critical for several spherical materials, both bare and water-reflected

• The solid line included is an empirical formula approximating the k_{eff} for each f



LA-14244-M




Figure 47. keff vs. Fraction of Critical Mass: Unreflected HEU and Pu Metal




Figure 48. k_{eff} vs. Fraction of Critical Mass: Water Reflected HEU and Pu Metal



LA-14244-M




Figure 49. keff vs. Fraction of Critical Mass: Bare HEU Solution




Figure 50. $k_{\rm eff}$ vs. Fraction of Critical Mass: Water Reflected HEU Solution



• LA-14244-M




Figure 51. keff vs. Fraction of Critical Mass: Bare Pu Solution




Figure 52. keff vs. Fraction of Critical Mass: Water Reflected Pu Solution



• For fast systems, both bare and reflected, a reasonable approximation of k_{eff} can be made using the following formula:

$$-k_{\text{eff}} = (f)^{\frac{1}{3}}$$

• For thermal systems, a reasonable approximation of k_{eff} can be made using the following formula:

$$-k_{\text{eff}} = (f)^{\frac{1}{4}}$$



- The critical mass of a bare sphere of α -phase ²³⁹Pu metal is ~10,000 g
 - A bare sphere consisting of 4,500 g of α -phase ²³⁹Pu metal has a fraction critical of:

•
$$f_{bare} = 4,500 \ g/10,000 \ g = 0.45$$

• Therefore, a bare sphere consisting of 4,500 g of α phase ²³⁹Pu metal has a k_{eff} that is about: • $k_{eff} = (0.45)^{\frac{1}{3}} = 0.77$

$$k_{eff} = (0.45)^{\frac{1}{3}} = 0.77$$



- The critical mass of a water-reflected sphere of α -phase ²³⁹Pu metal is ~5,400 g
 - A water-reflected sphere consisting of 4,500 g of α -phase ²³⁹Pu metal has a fraction critical of:

•
$$f_{refl.} = 4,500 \ g/5,400 \ g = 0.83$$

• Therefore, a water-reflected sphere consisting of 4,500 g of α -phase ²³⁹Pu metal has a k_{eff} that is about:

•
$$k_{eff} = (0.83)^{\frac{1}{3}} = 0.94$$



 The core density conversion method relates a critical core with a known density to an equivalent critical core with another density

Applies to systems with uniform densities

Applies to both bare and reflected conditions



The relationship is given by:

$$m_c = m_{co} \left[\frac{\rho}{\rho_o} \right]^{-s}$$

- Where s is determined by reflector conditions
- For a bare core, s equals 2
- For a reflected core, when both the core and reflector densities are changed by the same ratio, s also equals 2



 For a reflected core, when the reflector density stays the same, s is relatively constant over the range:

$$0.5 \le \frac{\rho}{\rho_o} \le 1$$

 The exponent s cannot exceed the value 2 that applies to a bare sphere



LA-3366




Fig. 15. Computed initial core-density exponents for water-reflected spheres of mixtures of water with ²³⁹Pu, U(93.5), U(30), U(5), or U(93.5)-graphite at C/²³⁵U = 157. Critical sizes are infinite where s = 2.

 Figure 15 shows values of s for water-reflected spheres with a density between normal and 0.8 times normal



- The water-reflected spherical critical mass of α -phase ²³⁹Pu metal (*density* = 19.86 g/cm³) is ~5,400 g
- What is the water reflected spherical critical mass of δ -phase ²³⁹Pu metal (*density* = 15.76 g/cm³)?

$$m_c = 5,400 g \left[\frac{15.76 g}{cm^3} \right]^{-1.5} = 7,600 g$$



- Converts a known critical shape to another critical shape consisting of the same material
- Originates from diffusion theory
- For a given material, shape conversion does NOT change material properties
- What changes is the neutron leakage, i.e., the shape of the neutron flux, which is related to the square of the geometric buckling, B_a^2



- To convert from one critical shape to another, we need a way to equate the neutron leakage associated with the two shapes
- Use geometric buckling equations for bare reactors
- Augmented by a "so-called" extrapolation distance, d
 - D NOT based diffusion theory
 - Look up value




Configuration	Geometry Illustration	Geometric Buckling $B_g{}^2$ Relationship
Sphere of Radius, r	<u> </u>	$\left(rac{\pi}{r+d} ight)^2$
Cylinder of Radius, <i>r</i> , and Height, <i>h</i>	h tr	$\left(\frac{2.405}{r+d}\right)^2 + \left(\frac{\pi}{h+2d}\right)^2$
Parallelepiped of Dimensions a, b , and c	a b	$\left(\frac{\pi}{a+2d}\right)^2 + \left(\frac{\pi}{b+2d}\right)^2 + \left(\frac{\pi}{c+2d}\right)^2$
Infinite Cylinder of Radius, r		$\left(\frac{2.405}{r+d}\right)^2$
Infinite Slab of Thickness, <i>h</i>	h	$\left(\frac{\pi}{h+2d}\right)^{\!\!2}$



- Calculate the bare critical height and the corresponding critical mass of a stack of the HEU foils used on the hand stack critical assembly Planet
- Foil Specifications:
 - 69 g HEU metal each
 - Uranium enriched to 93.2 w/o U-235
 - 9" (22.9 cm) W x 9" (22.9 cm) L x 0.003" (0.00762 cm) thick
 - Assume U(93) metal has a density of 18.75 g/cm³



Illustration of the Planet Handstack Assembly





- Bare sphere of U(93) metal:
 - Critical mass ~50 kg

$$\frac{50,000 g}{18.75 g/cm^3} = V_s = \frac{4}{3} \pi r_s^3$$

$$r_s = \left(\frac{(3)(50,000 g)}{(18.75 g/cm^3)(4)(\pi)}\right)^{1/3} = 8.6 cm$$



 To calculate the critical mass of uranium foils for the planet assembly:


$$B_g^2 \text{ (sphere)} = \left(\frac{\pi}{r+d}\right)^2$$

$$B_g^2 \text{ (cuboid)} = \left(\frac{\pi}{a+2d}\right)^2 + \left(\frac{\pi}{b+2d}\right)^2 + \left(\frac{\pi}{c+2d}\right)^2$$

$$B_g^2 \text{ (sphere)} = B_g^2 \text{ (cuboid)}$$

$$\left(\frac{\pi}{r+d}\right)^2 = \left(\frac{\pi}{a+2d}\right)^2 + \left(\frac{\pi}{b+2d}\right)^2 + \left(\frac{\pi}{c+2d}\right)^2$$







Solve the buckling equation for c (finite slab thickness):

$$d \approx 2.2 \text{ cm}$$

$$c = \left[\frac{1}{\left(r_{sph} + d \right)^2} - \frac{1}{\left(a + 2d \right)^2} - \frac{1}{\left(b + 2d \right)^2} \right]^{-1/2} - 2d$$

$$c = \left[\frac{1}{(8.6 \text{ cm} + 2.2 \text{ cm})^2} - \frac{1}{(22.9 \text{ cm} + 2 \cdot 2.2 \text{ cm})^2} - \frac{1}{(22.9 \text{ cm} + 2 \cdot 2.2 \text{ cm})^2} \right]^{-1/2} - 2 \cdot 2.2 \text{ cm}$$

$$c = 13.03 \text{ cm} - 4.4 \text{ cm} = 8.63 \text{ cm}$$



Critical volume:

$$V_{critical} = 22.9 \text{ cm} \times 22.9 \text{ cm} \times 8.63 \text{ cm} = 4,526 \text{ cm}^3$$

$$m_{critical} = \rho \cdot V_{critical} = 18.75 \frac{g}{\text{cm}^3} \cdot 4526 \text{ cm}^3 = 84,857 \text{ g}$$



Why is this mass greater than the spherical critical mass (~50 kg)?

This equates to 79,087 g of U-235 in U(93.2) metal.

More than 1,229 foils are required to achieve criticality with this system.



Illustration of the Planet Handstack Assembly

