

Wimsatt Welder Repair

150 Beveridge Rd
Seguin TX 78155
(502)-650-7484

Estimate

Submitted on 3/20/2026

Invoice for

Brian Atkinson
Atkinson welding and fabrication.

Payable to

Name

customer #

8725

Project

Hobart Champ 10k camo.

received Date

3/18/2026

Description	Qty	Unit price	Total price
New ELECTRIC fuel pump.	1	\$120.00	\$120.00
fuel lines	1	\$15.00	\$15.00
fuel filter	1	\$9.00	\$9.00
fuse holder	1	\$25.00	\$25.00
fuses	1	\$16.00	\$16.00
oil change -synthetic	1	\$65.00	\$65.00

oil disposal	1	\$15.00	\$15.00
shop supplies	1	\$35.00	\$35.00
rebuild carburetor	1	\$50.00	\$50.00
new air filter	1	\$40.00	\$40.00
air filter box cover Nut	1	\$40.00	\$40.00
Parts			\$430.00
Labor	12	\$100.00	\$1,200.00

Notes:

fuel pump failure, causing gas to enter oil in crankcase. carburetor cleaning required, needs a battery. breather box nut missing. electric fuel pump will prevent gas from getting into the oil. also needs some battery terminals and a group 58 battery. lawnmower batteries are insufficient for proper function.

Subtotal **\$1,630.00**

Tax: 6.75% **\$110.03**

\$1,740.03