CONTACT

Firmware 64

Firmware hacking and breaking

Solution for 'multiple definition of yylloc' error

8 August, 2020 • Banana Pi M4 • devel

When building BPi-M4 BSP, if you are facing the following error,

```
usr/bin/ld: scripts/dtc/dtc-
parser.tab.o:(.bss+0x10): multiple
definition of 'yylloc'; scripts/dtc
/dtc-lexer.lex.o:(.bss+0x0): first
defined here
```

collect2: error: ld returned 1 exit
status

edit the file ./linux-rtk/scripts/dtc/dtc-lexer-lex.c
Find the line 'YYLTYPE yylloc' and change it to
'extern YYLTYPE yylloc'

reference: https://lkml.org/lkml/2020/4/1/1206

SEARCH

CATEGORIES

Banks (1)

Benchmarks (1)

Banana Pi M4 (1)

Consumer

Electronics (1)

Manjaro Linux (1)

Mumble (2)

Raspberry Pi Pico (1)

Windows 10 (1)

1 of 2 28/01/2023, 16:38

Copyright © 2022 fw64.net

2 of 2 28/01/2023, 16:38