Peirce's criterion for the elimination of suspect experimental data

Stephen M. Ross, Ph.D.

Journal of Engineering Technology, Fall 2003.

Professor of Mechanical Engineering, University of New Haven, 300 Orange Ave., West

Haven, CT 06516

ABSTRACT

Peirce's criterion is a rigorous method based on probability theory that can be used to eliminate data "outliers" or spurious data in a rational way. Currently, another method called Chauvenet's criterion is used in many educational institutions and laboratories to perform this function. Although Chauvenet's criterion is well established, it makes an arbitrary assumption concerning the rejection of the data. Peirce's criterion does not make this arbitrary assumption. In addition, Chauvenet's criterion makes no distinction between the case of one or several suspicious data values whereas Peirce's criterion is a rigorous theory that can be easily applied in the case of *several suspicious data values*. In this paper, an example is given showing that Peirce's and Chauvenet's criterion give different results for the particular set of data presented.

INTRODUCTION

Peirce's criterion has been buried in the scientific literature for approximately 150 years. It is virtually unknown today in the scientific community. In its place, Chauvenet's criterion is commonly used for rational elimination of "outlier" data by government laboratories, (e.g., Environmental Protection Agency, U.S. Army Corps of Engineers,

Agency for Toxic Substances and Disease Registry, Institute for Telecommunication Sciences), industry (e.g., Boeing, Sikorsky), foreign laboratories (e.g., Laboratoire National Henri Becquerel, Joint Astronomy Centre), and universities (e.g., research and courses at University of Michigan, Texas A&M, University of California, Vanderbilt, University of Alberta, Ohio State).

Methods of elimination of data "outliers" are useful for anyone working in industry or in an educational institution where statistical information concerning product runs or experimental data is of interest. In an engineering, technology or science program, laboratory courses in chemistry, physics and engineering can, and do, find use for rational spurious data elimination.

In the BSME program at the University of New Haven, we have used Chauvenet's criterion in our instrumentation and fluid/thermal laboratory courses for many years. Other universities have similarly used this criterion in their undergraduate laboratories. Typically, students take several measurements of a quantity, say pressure, at one setting (meaning the experimental conditions are maintained at the same level). Assuming the systematic errors are negligible, each measurement will vary slightly due to random errors (e.g., reading instrument values, flow rate may change slightly, etc.). Often, however, one or two datum points seem to fall "far" outside the range of the others obtained. These outliers greatly impact the mean and standard deviation of the measurements. A data elimination method can be used to obtain a realistic average value of pressure and an "uncertainty" in the true value given by the standard deviation.

BACKGROUND

In the course of taking experimental data, there is often the situation in which one or more of the data values seems intuitively to be well outside of the norm expected.

Whatever the reasons for this occurrence, whether due to a temporary equipment glitch or not, a rational method can be used to eliminate the data point(s) in question.

This problem was originally addressed by Peirce ¹, Gould ², and later by Chauvenet ³ in 1863. All of them used elements of probability theory to develop a logical method to eliminate suspicious data from a set of measurements.

Chauvenet's criterion is in common use today for elimination of suspect data. Among other texts, it can be found in different, but equivalent, form in Holman's book on experimental methods ⁴ and Taylor's text ⁵ on error analysis. In Chauvenet's method, there is an arbitrary assumption that a measurement may be rejected if the probability of obtaining the deviation from the mean for that value is less than the inverse of twice the number of measurements. The theoretical development of Peirce's criterion does not make any such assumption. In addition, whereas Chauvenet's criterion makes no distinction between the case of one or several suspicious data values, Peirce's criterion is a rigorous theory that can be easily applied in the case of *several suspicious data values* using the table in this paper.

Chauvenet himself believed that Peirce's work was more rigorous and could be applied more generally, and in Chauvenet's words, "For the general case..... when there are several unknown quantities and several doubtful observations, the modifications which the rule (meaning his own criterion) requires renders it more troublesome than Peirce's

formula.....What I have given may serve the purpose of giving the reader greater confidence in the correctness and value of Peirce's Criterion". ³

Peirce's criterion is an in-depth derivation formulated directly from the theory of probability. It was based on the following principle: "...the proposed observations should be rejected when the probability of the system of errors (my note: the actual deviations from the mean) obtained by retaining them is less than that of the system of errors obtained by their rejection multiplied by the probability of making so many, and no more, abnormal observations". ¹ The actual method of calculation used by Peirce was mathematically cumbersome to use and a later paper by Gould took Peirce's criterion and presented it in a more easily usable format with tables he derived from Peirce's work.

The table of Peirce's criterion for one measured quantity is reproduced here in modified form covering up to a maximum of 60 total measurements. It is denoted as "Peirce's Criterion Table" in this paper. ⁶

In the table, R represents the ratio of the maximum allowable deviation of a measured value from the data mean to the standard deviation. That is,

$$R = \frac{|x_i - x_m|_{\max}}{\sigma} \tag{1}$$

where σ is the "sample" standard deviation of the complete data set,

 x_i is a measured data value, and

 x_m is the mean of the data set.

PEIRCE'S METHOD

The method to determine whether data values should be rejected involves the procedure outlined below:

- 1. Calculate the mean and the sample standard deviation of the complete data set.
- Obtain R corresponding to the number of measurements taken from Peirce's table.
 Assume the case of <u>one</u> doubtful observation first, even if there appears to be more than one
- 3. Calculate the maximum allowable deviation: $|x_i x_m|_{max}$.
- 4. For any suspicious data measurements, obtain $|x_i x_m|$.
- 5. Eliminate the suspicious measurements if:

$$|x_i - x_m| > |x_i - x_m|_{max}. \tag{2}$$

- 6. If this results in the rejection of one measurement, assume the case of <u>two</u> doubtful observations, keeping the original values of the mean and standard deviation, and the original number of measurements. Go to step 8.
- 7. If more than one measurement is rejected in the above test, assume the next highest value of doubtful observations. For example, if two measurements are rejected in

- step 5, assume the case of <u>three</u> doubtful observations, keeping the original values of the mean, standard deviation, and the original number of measurements as the process is continued.
- 8. Repeat the above calculations (steps 2 5), sequentially increasing the number of doubtful measurement possibilities, until no more data measurements need to be eliminated.
- 9. Now obtain the new value of the mean and sample standard deviation of the reduced data set

EXAMPLE: PEIRCE'S CRITERION

In this example, one of the datum points will be rejected using Peirce's criterion. A comparison using Chauvenet's criterion gives a different result for this particular set of data. None of the ten data values are eliminated using Chauvenet's criterion.

Ten pressure measurements are taken in an experiment at one setting. The gage values are 101.2, 90.0, 99.0, 102.0, 103.0, 100.2, 89.0, 98.1, 101.5, 102.0 kPa. The pressures of 89.0 and 90.0 appear suspect. We follow Peirce's method in the steps below.

- 1. Determine the sample standard deviation and mean for the complete set: $\sigma = 5.02$, $x_m = 98.6$.
- 2. Obtain R from the table for one measured quantity assuming one doubtful observation and ten measurements: R = 1.878. (Note that it is possible that more than one measurement may be eliminated in this first round of checking.)
- 3. Calculate the maximum allowable deviation:

$$|x_i - x_m|_{max} = \sigma R = 5.02 (1.878) = 9.43.$$

4. Obtain the actual deviations for the suspicious measurements:

$$|89 - x_m| = |89.0 - 98.6| = 9.60.$$

$$|90 - x_m| = |90.0 - 98.6| = 8.60.$$

5. Check for elimination of the suspicious data using equation 2:

9.60 > 9.43 Eliminate this datum measurement (89.0).

8.60 < 9.43 Retain this datum measurement (90.0).

6. Now repeat the above assuming two doubtful data measurements.⁷ From the table, second column, still using the ten observation row: R = 1.570. Obtain the maximum allowable deviation using the original standard deviation and mean: $|x_i - x_m|_{\text{max}} = \sigma R$ = 5.02 (1.570) = 7.88.

Check for elimination of suspect point 90.0: $|90 - x_m| = |90.0 - 98.6| = 8.60$.

Since 8.60 > 7.88, eliminate the measurement 90.0. No other measurements are eliminated at this step.

7. To consider rejecting a third measurement, repeat this process using the third column from the table with the row still corresponding to ten observations: R = 1.380. Obtain the maximum allowable deviation using the original standard deviation and mean: $|x_i - x_m|_{max} = \sigma R = 5.02 (1.380) = 6.93$.

A check of $|x_i - x_m|$ for the remaining eight observations shows that no other measurements need to be eliminated. *This concludes the process of elimination*.

8. For the final result, re-calculate the sample standard deviation and the mean for the reduced data set of 8 remaining observations (i.e., the original set with points 89.0 and 90.0 eliminated): $\sigma = 1.66$, $x_m = 100.9$.

An analysis using Chauvenet's criterion for the same data set does <u>not</u> reject the two suspect data values above. From table 3.5, P. 79 from Holman's text⁵, we have the maximum acceptable deviation to standard deviation ratio of 1.96. Thus, $|x_i - x_m|_{max} = 5.02 (1.96) = 9.84$. Referring back to step 4 above, we have $|89 - x_m|$ and $|90 - x_m|$ equal to 9.60 and 8.60, both of which are acceptable; none of the ten datum values are eliminated.

SUMMARY AND CONCLUSION

Chauvenet's criterion, commonly used today for the rational elimination of datum "outliers" was preceded by the more rigorous, and more general, Peirce's criterion.

It is recommended that Peirce's criterion be used instead of Chauvenet's criterion for the elimination of suspect data for the following reasons:

- Peirce 's formulation is more rigorous.
- Peirce's criterion does not make an arbitrary assumption concerning the rejection of data.
- Peirce's criterion theoretically accounts for the case where there is more than one suspect observation. Chauvenet's criterion does not.
- Peirce's method can be easily followed using the table in this paper.

A modified version of Peirce's criterion in table form along with a detailed example illustrating how to apply the criterion for a set of data measurements is reproduced in this paper. Peirce's criterion gives a different result than Chauvenet's criterion for this

particular set of data. The table contains values for up to 60 total measurements with one to nine doubtful observations for one type of measured unknown quantity.

The author wishes to thank Professors John Sarris and John R.Taylor for their helpful criticism in preparation of this paper.

FOOTNOTES AND REFERENCES

- ¹ Benjamin Peirce, " Criterion for the rejection of doubtful observations, " Astronomical Journal II, **45**, 161-163 (1852).
- ² B.A. Gould, "On Peirce's criterion for the rejection of doubtful observations, with tables for facilitating its application," Astronomical Journal IV, **83**, 81 87 (1855).
- ³ William Chauvenet, A Manual of Spherical and Practical Astronomy V.II, Lippincott, Philadelphia, 1st Ed (1863); Reprint of 1891 5th Ed: Dover, NY (1960).
- ⁴ John Taylor, *Error Analysis*, 2nd Ed, pp. 166 170, University Sci. Books, Sausalito, CA (1997).
- ⁵ J.P. Holman, *Experimental Methods for Engineers*, 7th Ed, pp. 78 80, McGraw Hill (2001).
- ⁶ The case of measurements for two different quantities appears to be relevant only to certain types of astronomical data. The original, and only, example that pertains to this case appears in Peirce's paper. The true meaning of the term "two unknown quantities" is not clear; however, it seems to pertain to both direct and indirect angle measurements. This same unclear example is exactly repeated in Gould's paper and Chauvenet's book. For typical experimental measurements in various disciplines, only the table for one unknown quantity is useful.
- ⁷ If both measurements were eliminated in step 5, the process would move on to the third column of the table in step 6 of the example.

PEIRCE'S CRITERION TABLE

ONE MEASURED QUANTITY

VALUES OF R

Total number									
of observati	ons	Number of doubtful observations							
	1	2	3	4	5	6	7	8	9
3	1.196								
4	1.383	1.078							
5	1.509	1.200							
6	1.610	1.299	1.099						
7	1.693	1.382	1.187	1.022					
8	1.763	1.453	1.261	1.109					
9	1.824	1.515	1.324	1.178	1.045				
10	1.878	1.570	1.380	1.237	1.114				
11	1.925	1.619	1.430	1.289	1.172	1.059			
12	1.969	1.663	1.475	1.336	1.221	1.118	1.009		
13	2.007	1.704	1.516	1.379	1.266	1.167	1.070		
14	2.043	1.741	1.554	1.417	1.307	1.210	1.120	1.026	
15	2.076	1.775	1.589	1.453	1.344	1.249	1.164	1.078	
16	2.106	1.807	1.622	1.486	1.378	1.285	1.202	1.122	1.039
17	2.134	1.836	1.652	1.517	1.409	1.318	1.237	1.161	1.084
18	2.161	1.864	1.680	1.546	1.438	1.348	1.268	1.195	1.123
19	2.185	1.890	1.707	1.573	1.466	1.377	1.298	1.226	1.158
20	2.209	1.914	1.732	1.599	1.492	1.404	1.326	1.255	1.190

21	2.230	1.938	1.756	1.623	1.517	1.429	1.352	1.282	1.218
22	2.251	1.960	1.779	1.646	1.540	1.452	1.376	1.308	1.245
23	2.271	1.981	1.800	1.668	1.563	1.475	1.399	1.332	1.270
24	2.290	2.000	1.821	1.689	1.584	1.497	1.421	1.354	1.293
25	2.307	2.019	1.840	1.709	1.604	1.517	1.442	1.375	1.315
26	2.324	2.037	1.859	1.728	1.624	1.537	1.462	1.396	1.336
27	2.341	2.055	1.877	1.746	1.642	1.556	1.481	1.415	1.356
28	2.356	2.071	1.894	1.764	1.660	1.574	1.500	1.434	1.375
29	2.371	2.088	1.911	1.781	1.677	1.591	1.517	1.452	1.393
30	2.385	2.103	1.927	1.797	1.694	1.608	1.534	1.469	1.411
31	2.399	2.118	1.942	1.812	1.710	1.624	1.550	1.486	1.428
32	2.412	2.132	1.957	1.828	1.725	1.640	1.567	1.502	1.444
33	2.425	2.146	1.971	1.842	1.740	1.655	1.582	1.517	1.459
34	2.438	2.159	1.985	1.856	1.754	1.669	1.597	1.532	1.475
35	2.450	2.172	1.998	1.870	1.768	1.683	1.611	1.547	1.489
36	2.461	2.184	2.011	1.883	1.782	1.697	1.624	1.561	1.504
37	2.472	2.196	2.024	1.896	1.795	1.711	1.638	1.574	1.517
38	2.483	2.208	2.036	1.909	1.807	1.723	1.651	1.587	1.531
39	2.494	2.219	2.047	1.921	1.820	1.736	1.664	1.600	1.544
40	2.504	2.230	2.059	1.932	1.832	1.748	1.676	1.613	1.556
41	2.514	2.241	2.070	1.944	1.843	1.760	1.688	1.625	1.568
42	2.524	2.251	2.081	1.955	1.855	1.771	1.699	1.636	1.580
43	2.533	2.261	2.092	1.966	1.866	1.783	1.711	1.648	1.592
44	2.542	2.271	2.102	1.976	1.876	1.794	1.722	1.659	1.603
45	2.551	2.281	2.112	1.987	1.887	1.804	1.733	1.670	1.614
46	2.560	2.290	2.122	1.997	1.897	1.815	1.743	1.681	1.625
47	2.568	2.299	2.131	2.006	1.907	1.825	1.754	1.691	1.636

48	2.577	2.308	2.140	2.016	1.917	1.835	1.764	1.701	1.646
49	2.585	2.317	2.149	2.026	1.927	1.844	1.773	1.711	1.656
50	2.592	2.326	2.158	2.035	1.936	1.854	1.783	1.721	1.666
51	2.600	2.334	2.167	2.044	1.945	1.863	1.792	1.730	1.675
52	2.608	2.342	2.175	2.052	1.954	1.872	1.802	1.740	1.685
53	2.615	2.350	2.184	2.061	1.963	1.881	1.811	1.749	1.694
54	2.622	2.358	2.192	2.069	1.972	1.890	1.820	1.758	1.703
55	2.629	2.365	2.200	2.077	1.980	1.898	1.828	1.767	1.711
56	2.636	2.373	2.207	2.085	1.988	1.907	1.837	1.775	1.720
57	2.643	2.380	2.215	2.093	1.996	1.915	1.845	1.784	1.729
58	2.650	2.387	2.223	2.101	2.004	1.923	1.853	1.792	1.737
59	2.656	2.394	2.230	2.109	2.012	1.931	1.861	1.800	1.745
60	2.663	2.401	2.237	2.116	2.019	1.939	1.869	1.808	1.753