
Bankfull-discharge sensitivity
Change in mean HCI (%)
125
100
75
50
25
0
−25
−50
HYK
JHT
GC
0.8Qbank
0.9Qbank
1.0Qbank
1.1Qbank
1.2Qbank
Activation-steepness sensitivity
Change in mean HCI (%)
60
40
20
0
−20
beta=5
beta=7
beta=8.7888983
beta=10
beta=12