



WARRANTY REQUEST FORM

Claim Date
2026.02.04.

COMPANY	Racing Parts Kft
EMAIL	hello@lmsperformance.eu
ORDER REFERENCE	DMZMPLXLX
PRODUCT REFERENCE	CTS-EXH-DP-0039
DATE OF PURCHASE	2025.11.13.
FINAL CONSUMER NAME AND ADDRESS	TIME-SPEED BT 1151. Budapest, Hungary, Szlacsányi Ferenc utca 3

FINAL SALES / INSTALL DATE	2025.11.21./2026.02.03.
VEHICLE BRAND	Audi
VEHICLE MODEL	RS5 B9
VEHICLE YEAR	2022
VEHICLE ENGINE CODE	DEC039242
VIN	WUAZZZF56PA900509
LHD OR RHD	LHD

DESCRIPTION OF THE PROBLEM	
The left hand side pipe not fit the OEM exhaust system. The flange on the CTS product is not in correct position.	
Please send photos and videos of your issue along with this warranty request to: sales@all-stars-distribution.com. Our team will respond to you shortly.	

INTERNAL USE	