





PREPARE SURFACES FOR SLIP-CRITICAL CONN. WHERE INDICATED. DO NOT PAINT AREAS OF SC CONNECTION.









ONE - COLUMN - 20C106