



PREPARE SURFACES FOR SLIP-CRITICAL CONN. WHERE INDICATED. DO NOT PAINT AREAS OF SC CONNECTION.



ONE - BEAM - 20B187