

## **PARTS IDENTIFICATION**

FID2505	Date: 14/10/14
RVS-QR- GLOT-001	
ED.:04	Pag.: 1 of 2

	P/N	M/T	DESCRIPTION	RoHs
FRU P/N	40X5167	7526	FLATBED SCANNER, COMPLETE	
Mnf P/N		7520	FLATBED SCANNER, COMPLETE	



**COMMENTS** 

**INCLUDE INSTRUCTION SHEET:14G0064** 

**CLEAR NVRAM** 

This document is an uncontrolled copy, for reference only.

CONFIDENTIAL - The information contained in this document is the intellectual property of syncreon Holdings, Ltd; disclosure to third parties is prohibited.



## **PARTS IDENTIFICATION**

FID2505	Date: 14/10/14
RVS-QR- GLOT-001	
ED.:04	Pag.: 2 of 2

Packaging	Vendor	syncreon
BOX	3046027	N/A
SIZE	RSC 675 x 540 x 335	675 x 540 x335
INS. SHEET	14G0064	14G0064
FOAM		
BAG		POLY BAG



Flatbed Scanner Assembly



Place the unit in the bag and secure with tape.



Foam Cushions



Attached the foam cushions to the unit.



Place the unit in the carton.Add Instruction Sheet 14G0064



Close the carton and seal with tape. Add labels.