

Sony XM6 headphone hinge repair

V Viktor

VIEW IN BROWSER

updated 23. 5. 2026 | published 23. 5. 2026

Summary

Part which can be used to reinforce broken hinge ring for Sony XM6

0.20 hrs	1 pcs	0.20 mm	0.40 mm	PLA	5 g	Sovol SV06

Gadgets > Audio

Tags: headphones headset repair

Both rings that support the headphone extension broke due to their flimsy design. The rings flexed and eventually failed under stress.

I modeled the dimensions in Fusion 360 and designed a pair of clamp reinforcements. After installing the clamps, everything works great - the headphones themselves are still solid and the folding mechanism function is unchanged.

The parts print with minimal supports on a Sovol SV06 using generic Kingroon PLA, print time is about 10 minutes on my setup. I’ve included the G-code file.

Once printed, you'll need a couple of small M2×20 mm bolts to clamp them in place.

Update 23.05.2026: i also added more beefier version, xm6_hinge_repair_rev3 file

Model files



xm6_hinge_repair-v28-rev2.3mf



xm6_hinge_repair_rev3.3mf

Print files

ssk_xm6_hinge_repair-v28-rev2.gcode

PLA 0.40 mm 0.20 mm 0.20 hrs 5 g

License

This work is licensed under a
Creative Commons (4.0 International License)

Attribution

✖ | Sharing without ATTRIBUTION
✔ | Remix Culture allowed
✔ | Commercial Use
✔ | Free Cultural Works
✔ | Meets Open Definition