Watchdog is used for low power sleep mode. Watchdog.enable() will enable the watchdow. This will turn on the watchdog timer and use the maximum countdown before resetting the Arduino. The value of this delay before reset (in milliseconds) is returned.
The watchdog is resetted before the countdown expires or the Arduino will reset. The timeout in the code is 16 seconds or 16000 milliseconds.