WO#: 2007 01772

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

91SA

1710

Cirrus

SR-20

692.0

RMS
Resource Maintenance System

Resource Maintenance System Work Order

Western Michigan University College of Aviation

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037 Date Started: 11/02/07
Date Completed: 11/02/07

A/C Total Time:	692.0
RT Eng. T.T.:	
RT Prop. T.T.	
LT Eng T.T.:	692.0
IT Prop TT:	692 (

Description of Work to be Performed						
1)	Flaps would not extend.					

1) Fla	ps would not extend.					
		Maintenance/Repairs Po	erformed			
1 ' -	s would not extend.					
Airframe						
Repl	aced flap up and down r	elays. Operational check good.				
		Labor				
Brian Sc	hmidt 0.5 000:30					
						0:30
		Parts Used				
Qty	Part#	Description	Serial#		Cost	Sub Total
2	50288-001	Relay, Flap or Circuit Panel (Alt P/N V23234-A0004-X051)			14.63	29.26
Technician Release				Work Order Totals		
Buy Back Test FLT Tech Signature: Tech#:			La	bor	30.00	
				Рa	rts	29.26
Maintenance Release			ТО	TAL:	59.26	
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair			Preliminary / Hidden Inspection Release			
Da	inder this Work Order. te: J FAA CertificatedRepair Station	Signed: JX8R258Q . 237 N Helmer Road, Battle Cre	eek. MI 49037	Date	e: pector:	