WO#: 2017 01111

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

91SA

1710

Cirrus

SR-20

5098.2

RMS
Resource Maintenance System

Resource Maintenance System Work Order

## Western Michigan University College of Aviation

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037 Date Started: 08/30/17
Date Completed: 08/31/17

A/C Total Time:	5098.2
RT Eng. T.T.:	
RT Prop. T.T.	
LT Eng T.T.:	1104.7
I T Prop T T ·	3251.7

		Description of Work to be Performed
1)	Left rear position bulb.	

i) Left fear position build.	•						
	Maintenance/Repairs	Performed					
1) Left rear position bulb. Airframe:							
Replaced LH rear position	n light bulb. Ops check good.						
	Labor						
Brian Schmidt 0.5 000:30							
	1				0:30		
	Parts Used						
Qty Part#	Description	Serial#		Cost	Sub Total		
1 34-0428070-64	White Position Light (A508-28)			22.80	22.80		
Technician Release				Work Order Totals			
Buy Back ☐ Test FLT ☐ Tech Signature: Tech#:				r s	30.00 22.80		
Maintenance Release			TOTAL:		52.80		
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order.		Preliminary / Hidden Inspection Release					
	Signed:ation JX8R258Q 237 N Helmer Road. Battle (		Date:	 or:			