WO#: 2022 00238

173WM

1739

Cirrus

SR-20

3702.8

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

RMS
Resource Maintenance System

Work Order Stern Michigan Unive

## Western Michigan University College of Aviation

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037 Date Started: 03/01/22
Date Completed: 03/08/22

A/C Total Time:	3702.8
RT Eng. T.T.:	
RT Prop. T.T.	
LT Eng T.T.:	3741.3
LT Prop T.T.:	3713.3

Description of Work to be Performed						
1)	ETA squawk: flap malfunction					

1) ETA	squawk: flap malfunction	1				
		Maintenance/Repairs Pe	erformed			
1 '	squawk: flap malfunction	•				
Airframe	:					
Remo	ved and replaced up and	down flap relays.				
		Labor				
Rusty Wi	nston 1.0 001:00					
						1:00
		Parts Used				
Qty	Part#	Description	Serial#		Cost	Sub Total
2	50288-001	Relay, Flap or Circuit Panel (Alt P/N V23234-A0004-X051)			13.75	27.50
Technician Release				Work Order Totals		
Buy Ba	ck Test FLT Tec	h Signature:	Tech#:	La	abor	75.00
		<u> </u>		Pa	ırts	27.50
Maintenance Release				TC	TAL:	102.50
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair			Preliminary / Hidden Inspection Release			
	under this Work Order. te:	Signed:		Da	te:	
		JX8R258Q . 237 N Helmer Road, Battle Cre	ek, MI 49037	Ins	pector:	