WO#: 2016 00745

Reg#:

MFG:

Model:

AC S/N:

Western Michigan University **College of Aviation**

Work Order

A/C Total Time: 4582.8 RT Eng. T.T.: RT Prop. T.T. LT Eng T.T.: 587.0 LT Prop T.T.: 2734.0

06/25/16

06/27/16

Date Started:

Date Completed:

A/C Tach Time: 4582.8

91SA

1710

Cirrus

SR-20

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

	Description of Work to be	Performed		
1) RH White Position Light I:	пор			
	M	e 1		
	Maintenance/Repairs Pe	erformed		
1) RH White Position Light In Airframe:	pp			
Replaced RH white position	light. Ground ops check good.			
	Labor			
Aaron Corona 1.0 001:00				
				1:00
	Parts Used			
Qty Part#	Description	Serial#	Cost	Sub Total
1 34-0428070-64	White Position Light (A508-28)		22.80	22.80
Technician Release			Work Order Totals	
Buy Back □ Test FLT □ Tech Signature: Tech#:			Labor Parts	60.00 22.80
Maintenance Release			TOTAL:	82.80
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair		stration and is	Preliminary / Hidden Inspection Release	
	Signed: on JX8R258Q . 237 N Helmer Road, Battle Cre	,	Date: nspector:	