WO#: 2015 00857

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

Work Order

## **Western Michigan University College of Aviation**

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

06/04/15 Date Started: Date Completed: 06/09/15

A/C Total Time: 4148.7 RT Eng. T.T.: RT Prop. T.T.

LT Eng T.T.: 163.7 LT Prop T.T.: 2310.7

91SA

1710

Cirrus

SR-20

4148.7

Zer Wildiner Read, Battle Groot, Wil 1888							
Description of Work to be Performed							
1) Lef	t and right strobe light	out					
Maintenance/Repairs Performed							
1) Left Airframe	and right strobe light:	out					
Installed new whelen power supply in RH wingtip. Installed new nav bulbs in LH wing. Ops check good.							
Labor							
John Fra	anklin 2.3 002:15						
Total Labor Hours: 2.3 2:15							
Parts Used							
Qty	Part#	Description	Serial#		Cost	Sub Total	
1	CMA7512-24	Bulb, Wing Nav (MS25309-7212 or W1290-28 or W1290-24)			15.91	15.91	
1	34-0428070-64	White Position Light (A508-28)			22.80	22.80	
1	50625-001	Strobe Power Supply (Alt P/N 01-0770062-05)			456.00	456.00	
Technician Release				Work Order Totals			
Buy Back Test FLT Tech Signature: Tech#:				La	.bor	135.00	
					rts.	494.71	
Maintenance Release				TO	TAL:	629.71	
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair					Preliminary / Hidden Inspection Release		
Station under this Work Order.				Date:			
Date: Signed: WMU FAA CertificatedRepair Station JX8R258Q . 237 N Helmer Road, Battle Creek, MI 49037				Inspector:			