WO#: 2021 00373

91SA

1710

Cirrus

SR-20

6865.0

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

Work Order

Western Michigan University College of Aviation

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

03/15/21 Date Started: Date Completed: 03/15/21

A/C Total Time: 6865.0 RT Eng. T.T.:

RT Prop. T.T.

LT Eng T.T.: 660.6 LT Prop T.T.: 5236.3

Description of Work to be Performed					
1) R po	osition light inop				
Maintenance/Repairs Performed					
1) R position light inop Airframe: Installed new R position light bulb. Ops check good.					
Labor					
Jonathan Dennis	1.0 001:00				1:00
Parts Used					
Qty	Part#	Description	Serial#	Cost	Sub Total
1	34-0428070-64	White Position Light (A508-28)		41.99	41.99
Technician Release				Work Order Totals	
Buy Back Test FLT Tech Signature: Tech#:				Labor Parts	75.00 41.99
Maintenance Release				TOTAL:	116.99
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order.				Preliminary / Hidden Inspection Release Date:	
Date: Signed: WMU FAA CertificatedRepair Station JX8R258Q . 237 N Helmer Road, Battle Creek, MI 49037				Inspector:	