WO#: 2008 01061

RIMS
Resource Maintenance System
Work Order

 Reg#:
 191JG

 AC S/N:
 1699

 MFG:
 Cirrus

 Model:
 SR-20

 A/C Tach Time:
 898.8

Western Michigan University College of Aviation

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037 Date Started: 05/12/08

Date Completed: 05/12/08

A/C Total Time: 898.8

A/C Total Time: 898. RT Eng. T.T.:

RT Prop. T.T.

LT Eng T.T.: 898.8

LT Prop T.T.: 898.8

| | Description of Work to be Performed |
|--------------|-------------------------------------|
| ot coming up | |

| 1) Flap | ps not coming up | | | | | |
|---|--------------------------|--|--------------|--|----------------|-----------|
| | | Maintenance/Repairs Pe | rformed | | | |
| 1) Flaps | s not coming up | | | | | |
| Could | d not duplicate on groun | nd. Replaced up and down flap relay | switches. | | | |
| | | Labor | | | | |
| Scott Aus | stin 0.5 000:30 | | | | | 0:30 |
| | | Parts Used | | | | |
| Qty | Part# | Description | Serial# | | Cost | Sub Total |
| 2 | 50288-001 | Relay, Flap or Circuit Panel (Alt P/N V23234-A0004-X051) | | | 14.63 | 29.26 |
| Technician Release | | | | Work Order Totals | | |
| Buy Back Test FLT Tech Signature: Tech#: | | | | abor arts | 30.00 29.26 | |
| Maintenance Release | | | | TC | TOTAL: 59 | |
| The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order. | | | | Preliminary / Hidden Inspection Release | | |
| Dat | te: | Signed: | ek, MI 49037 | Dat | te: pector: | |