WO#: 2019 01765

Reg#:

MFG:

Model:

AC S/N:

Work Order

Western Michigan University College of Aviation

A/C Total Time: 6214.4 RT Eng. T.T.: RT Prop. T.T. LT Eng T.T.: 2217.4 LT Prop T.T.: 4364.4

Date Started:

Date Completed:

10/15/19

10/15/19

A/C Tach Time: 6214.4

91SA

1710

Cirrus

SR-20

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

Description of Work to be Performed				
1) Left position light out.				
	Maintenance/Repairs Pe	erformed		
1) Left position light out. Airframe: Replaced LH white position				
	Labor			
Pam Jones 0.5 000:30				0:30
	Parts Used			
Qty Part#	Description	Serial#	Cost	Sub Total
1 34-0428070-64	White Position Light (A508-28)		37.0	4 37.04
Technician Release			Work Order Totals	
Buy Back ☐ Test FLT ☐ Tech Signature: Tech#:		Labor Parts	30.00 37.04	
Maintenance Release			TOTAL:	67.04
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order.		Preliminary / Hidden Inspection Release Date:		
Date: WMU FAA CertificatedRepair Station	Signed:	ek, MI 49037	Inspector:	