WO#: 2020 01259

91SA

1710

Cirrus

SR-20

6635.6

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

RMS
Resource Maintenance System

Resource Maintenance System Work Order

Western Michigan University College of Aviation

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037 Date Started: 10/27/20
Date Completed: 10/29/20

A/C Total Time: 6635.6

RT Eng. T.T.:

RT Prop. T.T.

LT Eng T.T.: 430.0

LT Prop T.T.: 5005.7

Description of Work to be Performed						
1) ETA squawk: flaps would not extend on approach						
Maintenance/Repairs Performed						
1) ETA squawk: flaps would not extend on approach Avionics: r/r relay						
Labor						
Kevin Sol	t 1.0 001:00					1:00
Parts Used						
Qty	Part#	Description	Serial#		Cost	Sub Total
2 50288-001 Relay, Flap or Circuit Panel (Alt P/N V23234-A0004-X051)					13.88	27.76
Technician Release				Work Order Totals		
Buy Back Test FLT Tech Signature: Tech#: Tech#:					bor rts	75.00 27.76
Maintenance Release				TOTAL:		102.76
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order. Preliminary / Hid Inspection Releases						•
Date: Signed: Date: Date: Inspector:						