WO#: 2019 00740

91SA

1710

Cirrus

SR-20

5928.6

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

Work Order

Western Michigan University College of Aviation

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

05/28/19 Date Started: Date Completed: 05/30/19

A/C Total Time:	5928.6
RT Eng. T.T.:	
RT Prop. T.T.	
LT Eng T.T.:	1933.0
LT Prop T.T.:	4080.0

Description of Work to be Performed						
1)	RH White Nav light out					

1) RH W	hite Nav light out							
Maintenance/Repairs Performed								
1) RH Wh	ite Nav light out	•						
		e position bulb. Operational check	good.					
Labor								
Justine F	Oster 0.5 000:30				0:30			
Parts Used								
Qty	Part#	Description	Serial#	Cost	Sub Total			
1 3	34-0428070-64	White Position Light (A508-28)		31.6	31.66			
Technician Release				Work Order Totals				
Buy Bac	ck□ Test FLT□Tech	n Signature:	Tech#:	Labor Parts	37.50 31.66			
Maintenance Release			TOTAL:	69.16				
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order.			Preliminary / Hidden Inspection Release Date:					
	e:\$ FAA CertificatedRepair Station J	Signed: X8R258Q . 237 N Helmer Road, Battle Cre	ek, MI 49037					