WO#: 2009 00570

Reg#:

MFG:

AC S/N:

**Western Michigan University College of Aviation** 

Work Order

A/C Total Time: 1499.8 RT Eng. T.T.: RT Prop. T.T. LT Eng T.T.: 1499.8 LT Prop T.T.: 1499.8

Date Started:

Date Completed:

03/30/09

03/30/09

SR-20 Model: A/C Tach Time: 1499.8

91SA

1710

Cirrus

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

Description of Work to be Performed							
1) fla	aps do not work						
Maintenance/Repairs Performed							
1) flaps do not work Airframe:							
replaced defective flap relays							
Labor							
Jacob El	lenbaas 0.5 000:30						
						0:30	
Parts Used							
Qty	Part#	Description	Serial#		Cost	Sub Total	
1/2	50288-001	Relay, Flap or Circuit Panel (Alt P/N V23234-A0004-X051)			14.63	14.63	
1/2	50288-001	Relay, Flap or Circuit Panel (Alt			14.63	14.63	
		P/N V23234-A0004-X051)					
Technician Release				Work Order Totals			
Buy Back ☐ Test FLT ☐ Tech Signature: Tech#:					oor	30.00	
M-2-4					cts	29.26	
Maintenance Release				TOT	ral:	59.26	
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is					Preliminary / Hidden		
approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order.					Inspection	n Release	
					Date:		
Date: Signed: WMU FAA CertificatedRepair Station JX8R258Q . 237 N Helmer Road, Battle Creek, MI 49037					Inspector:		