WO#: 2019 01490

91SA

1710

Cirrus

SR-20

6165.4

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

Work Order

Western Michigan University College of Aviation

09/05/19 Date Started: Date Completed: 09/13/19

/C Total Time:	6165		
RT Eng. T.T.:			

RT Prop. T.T. LT Eng T.T.: 2182.5 LT Prop T.T.: 4329.5

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

Description of Work to be Performed								
1) LH]	position light inop							
		Maintenance/Repairs Pe	rformed					
1) LH po	osition light inop :							
Inst	alled new LH white posit	ion light bulb.						
		Labor						
Nathan S	tewart 0.5 000:30					0:30		
		Parts Used						
Qty	Part#	Description	Serial#		Cost	Sub Total		
1	34-0428070-64	White Position Light (A508-28)			37.04	37.04		
Technician Release			Work Order Totals					
Buy Ba	.ck 🗆 Test FLT 🗆 Tec	h Signature:	Tech#:	1 -	abor arts	37.50 37.04		
Maintenance Release			TOTAL:		74.54			
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order.		Preliminary / Hidden Inspection Release Date:						
Date: Signed: WMU FAA CertificatedRepair Station JX8R258Q . 237 N Helmer Road, Battle Creek, MI 49037					spector:			