WO#: 2015 00658

91SA

1710

Cirrus

SR-20

4101.1

Reg#:

MFG:

Model:

A/C Tach Time:

Station under this Work Order.

WMU FAA CertificatedRepair Station JX8R258Q

Date:

AC S/N:

RMS
Resource Maintenance System

Resource Maintenance System Work Order

Western Michigan University College of Aviation

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037 Date Started: 05/06/15
Date Completed: 05/13/15

A/C Total Time: 4101.1 RT Eng. T.T.:

LT Eng T.T.: 113.1 LT Prop T.T.: 2260.1

Preliminary / Hidden

Inspection Release

Date:

Inspector: .

RT Prop. T.T.

Description of Work to be Performed RH wing white position light inop. Maintenance/Repairs Performed 1) RH wing white position light inop. Airframe: Removed and replaced RH wing white position light bulb with a new one. Ground operational check satisfactory. Labor 002:00 Dave Mumford 2:00 **Parts Used** Qty Part# Description Serial# Cost Total White Position Light (A508-28) 22.45 34-0428070-64 22.45 **Work Order Totals Technician Release** Labor 120.00 Buy Back Test FLT Tech Signature: Tech#: 22.45 Parts **Maintenance Release** TOTAL: 142.45

. 237 N Helmer Road, Battle Creek, MI 49037

The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and

repaired in accordance with current Regulations of the Federal Aviation Administration and is

Signed:

approved for return to service. Pertinent details of the repair/inspection are on file at the Repair