WO#: 2017 01488

91SA

1710

Cirrus

SR-20

5208.2

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

Work Order

Western Michigan University College of Aviation

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

11/06/17 Date Started: Date Completed: 11/20/17

A/C Total Time:	5208.2
RT Eng. T.T.:	
RT Prop. T.T.	
LT Eng T.T.:	1240.
I T Prop T T ·	3387

	Description of Work to be Performed						
1)	RH White position light inop						

1) RH White position light	nop						
	Maintenance/Repairs F	erformed					
1) RH White position light in Airframe:	rob						
Replaced white position 1	ight bulb. Ops check good.						
	Labor						
Kevin Luther 1.0 001:00					1:00		
	Parts Used						
Qty Part#	Description	Serial#	C	Cost	Sub Total		
1 34-0428070-64	White Position Light (A508-28)			20.35	20.35		
Technician Release				Work Order Totals			
Buy Back ☐ Test FLT ☐ Tech Signature: Tech#:				-	75.00 20.35		
Maintenance Release			TOTAL:		95.35		
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order.			Preliminary / Hidden Inspection Release				
Date:	Signed: ion JX8R258Q . 237 N Helmer Road, Battle Ci	eek, MI 49037	Date:	 or:			