WO#: 2018 01438

173WM

1739

Cirrus

SR-20

2265.8

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

Work Order

## **Western Michigan University College of Aviation**

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

Date Started: 09/13/18 Date Completed: 09/13/18

A/C Total Time: 2265.8

RT Eng. T.T.: RT Prop. T.T.

LT Eng T.T.: 2293.8 LT Prop T.T.: 2265.8

	201 11110111101 11000, 201110 1			
Description of Work to be Performed				
1) Left aft navigation light	nt bulb is inoperative.			
Maintenance/Repairs Performed				
1) Left aft navigation light Airframe:	-	24 0400000 64 0		
_	left aft navigation light bulb P/N hed I.A.W. Cirrus SR20 AMM chapter 3	_	ked the lights	5
Labor				
David Ober 0.4 000:24				
	•			0:24
	Parts Used			
Qty Part#	Description	Serial#	Cost	Sub Total
1 F-34-0428070-64	Lamp, White Position (Alt P/N A508-28)		22.80	22.80
Technician Release			Work Order Totals	
Buy Back Test FLT Tech Signature: Tech#:		Tech#:	Labor	30.00
			Parts	22.80
Maintenance Release			TOTAL:	52.80
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order.			Preliminary / Hidden Inspection Release	
Date:	Signed: ation JX8R258Q . 237 N Helmer Road, Battle 0	,	Date: nspector:	

## Page 1 of 1 for Work Order 2018 01438