WO#: 2014 00575

91SA

1710

Cirrus

SR-20

3717.6

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

Work Order

Western Michigan University **College of Aviation**

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

Date Started: 05/12/14 Date Completed: 05/12/14

A/C Total Time: 3717.6 RT Eng. T.T.:

LT Eng T.T.: 1723.4 LT Prop T.T.: 3720.4

RT Prop. T.T.

Description of Work to be Performed						
1)	Left white position light inop.					

1) Left white position light	inop.				
	Maintenance/Repairs l	Performed			
1) Left white position light is	nop.				
Airframe:					
Replaced position light bul	b.				
	Labor				
Ian Henderson 0.8 000:45					
		Total I	Labor Hours:	0.8 0:45	
	Parts Used				
I Ohar I Basek II			Cost	Sub Total	
Qty Part#	Description Viels (2500.00)	Serial#			
1 34-0428070-64	White Position Light (A508-28)		20.8	5 20.85	
Technician Release				Work Order Totals	
Buy Back ☐ Test FLT ☐ Te	ch Signature:	Tech#:	Labor	56.25	
			Parts	20.85	
	TOTAL:	77.10			
The aircraft, airframe, aircraft engine	Preliminary / Hidden				
repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair				Inspection Release	
Station under this Work Order.	ient details of the repair/inspection are o	Tille at tile Nepali	mspeed	ion Release	
			Date:		
Date:	Signed:		1		