WO#: 2019 02018

173WM

1739

Cirrus

SR-20

2685.5

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

Work Order

Western Michigan University College of Aviation

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

12/07/19 Date Started: Date Completed: 12/10/19

A/C Total Time:	2685.
RT Eng. T.T.:	
RT Prop. T.T.	

LT Eng T.T.: 2717.1 LT Prop T.T.: 2689.1

Description of Work to be Performed								
1) LH	white postion light ino	p						
Maintenance/Repairs Performed								
1) LH w Airframe	white postion light inop							
Inst	talled new LH white posi	tion light bulb.						
Labor								
Nathan S	Stewart 0.5 000:30					0:30		
Parts Used								
Qty	Part#	Description	Serial#		Cost	Sub Total		
1	34-0428070-64	White Position Light (A508-28)			37.04	37.04		
Technician Release			Work Order Totals					
Buy Back ☐ Test FLT ☐ Tech Signature: Tech#:			Labor Parts		37.50 37.04			
Maintenance Release			TOTAL:		74.54			
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order.		Preliminary / Hidden Inspection Release						
Date: Signed: WMU FAA CertificatedRepair Station JX8R258Q . 237 N Helmer Road, Battle Creek, MI 49037				Date:				