WO#: 2013 00163

91SA

1710

Cirrus

SR-20

3140.1

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

RIMS
Resource Maintenance System
Work Order

Western Michigan University
College of Aviation

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037 Date Started: 02/20/13
Date Completed: 02/22/13

A/C Total Time: 3140.1 RT Eng. T.T.: RT Prop. T.T.

LT Eng T.T.: 1148.3 LT Prop T.T.: 3145.3

Description of Work to be Performed				
1) Left white nav out				
	Maintenance/Repairs	Performed		
1) Left white nav out Airframe:				
Removed and replaced LH Rear	nav bulb. Ops check good.			
	Labor			
Justine Foster 0.5 000:30				
				0:30
	Parts Used			
Qty Part#	Description	Serial#	Cost	Sub Total
1 34-0428070-64	White Position Light (A508-28)		22.8	30 22.80
Technician Release			Work Order Totals	
Buy Back ☐ Test FLT ☐ Tech Signature:		Tech#:	Labor	37.50
			Parts	22.80
Maintenance Release			TOTAL:	60.30
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order.			Preliminary / Hidden Inspection Release Date:	
Date: Signed: WMU FAA CertificatedRepair Station JX8R258Q . 237 N Helmer Road, Battle Creek, MI 49037 Inspector:				