WO#: 2019 00650

91SA

1710

Cirrus

SR-20

5890.5

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

RMS
Resource Maintenance System

Resource Maintenance System Work Order

Western Michigan University College of Aviation

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

Date Started: 05/14/19
Date Completed: 05/20/19

A/C Total Time:	5890.
RT Eng. T.T.:	
RT Prop. T.T.	
LT Eng T.T.:	1909.2

4056.2

LT Prop T.T.:

Description of Work to be Performed

1) Flaps stuck between 50 and up. Will not raise past.

1) Fla	ps stuck between 50 and	up. Will not raise past.				
		Maintenance/Repairs Pe	erformed			
1) Flap	s stuck between 50 and u	p. Will not raise past.				
Repl	aced flap relays. Operat	ional check good.				
		Labor				
Justine	Foster 1.0 001:00					1:00
		Parts Used				
Qty	Part#	Description	Serial#		Cost	Sub Total
2	50288-001	Relay, Flap or Circuit Panel (Alt P/N $V23234-A0004-X051$)			9.85	19.70
Technician Release			Work Order Totals			
Buy Ba	ack 🗌 Test FLT 🗌 Tec	h Signature:	Tech#:		bor rts	75.00 19.70
Maintenance Release			TO	TAL:	94.70	
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair		Preliminary / Hidden Inspection Release				
Da		Signed: JX8R258Q . 237 N Helmer Road, Battle Cre	ek, MI 49037	Dat	e: pector:	