WO#: 2021 00938

91SA

1710

Cirrus

SR-20

7046.4

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

RIMS
Resource Maintenance System

Work Order Vestern Michigan Univ

Western Michigan University College of Aviation

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037 Date Started: 06/17/21 Date Completed: 06/23/21

A/C Total Time: 7046.4 RT Eng. T.T.:

RT Prop. T.T.

LT Eng T.T.: 838.6 LT Prop T.T.: 5414.3

Description of Work to be Performed				
1) wht pos light inop LH				
Maintenance/Repairs Performed				
1) wht pos light inop LH Airframe:				
Replaced LH white position light bulb. Ops check good.				
Labor				
Kevin Luther 0.5 000:30				0:30
Parts Used				
Qty Part#	Description	Serial#	Cost	Sub Total
1 34-0428070-64	White Position Light (A508-28)		41.99	41.99
Technician Release			Work Order Totals	
Buy Back ☐ Test FLT ☐ Te	ch Signature:	Tech#:	Labor Parts	37.50 41.99
Maintenance Release			TOTAL:	79.49
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order.			Preliminary / Hidden Inspection Release Date:	
Date: Signed: WMU FAA CertificatedRepair Station JX8R258Q . 237 N Helmer Road, Battle Creek, MI 49037			Inspector:	