WO#: 2008 01392

Reg#:

MFG:

Model:

AC S/N:

RMS
Resource Maintenance System
Work Onder

191JG
1699
Cirrus
SR-20
Work Order
Work Order

Work Order

Work Order

Work Order

Work Order

Work Order

Work Order

Date Started: 06/14/08

Date Completed: 06/14/08

A/C Total Time: 984.2 RT Eng. T.T.:

RT Prop. T.T.

LT Eng T.T.: 984.2 LT Prop T.T.: 984.2

A/C Tach Time: 984.2 984.2 FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037 **Description of Work to be Performed** Before flight, and while completing the before taxi checklist the flaps would not fully 1) retract to zero degrees. Maintenance/Repairs Performed Before flight, and while completing the before taxi checklist the flaps would not fully retract to zero degrees. Airframe: Removed and replaced flap relays. Flaps operational check good. Labor Justine Foster 0.5 000:30 0:30 **Parts Used** Part# Description Serial# Cost Qty Sub Total 50288-001 Relay, Flap or Circuit Panel (Alt 14.63 29.26 P/N V23234-A0004-X051) **Work Order Totals Technician Release** 30.00 Buy Back ☐ Test FLT ☐ Tech Signature: Labor Tech#: Parts 29.26 **Maintenance Release** TOTAL: 59.26 The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and Preliminary / Hidden repaired in accordance with current Regulations of the Federal Aviation Administration and is **Inspection Release** approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order. Date: Signed: Inspector: . WMU FAA CertificatedRepair Station JX8R258Q . 237 N Helmer Road, Battle Creek, MI 49037