WO#: 2017 00556

191JG

1699

Cirrus

SR-20

4692.1

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

Work Order

## **Western Michigan University College of Aviation**

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

Date Started: 05/08/17 Date Completed: 05/10/17

A/C Total Time: 4692.1 RT Eng. T.T.: RT Prop. T.T.

LT Eng T.T.: 692.6 LT Prop T.T.: 692.6

	Description of Wo	rk to be P	Performed			
1) ETA squawk: Flap over	speed notification went off.					
	7. f. f. / / / / / / / / / / / / / / / /		<b>a</b> 1			
	Maintenance/Re	pairs Per	formed			
1) ETA squawk: Flap over s Airframe:	peed notification went off.					
	ng overspeed condition. NDN. several times. Ops check good		new flap relays a	fter	intermitter	nt
	La	bor				
Curran McGuire 1.0 001:0	0					1:00
	Parts	Used				
Oty Part#	Description		 Serial#	Ī	Cost	Sub Total
2 50288-001	Relay, Flap or Circuit Pa P/N V23234-A0004-X051)	anel (Alt			10.25	20.50
Technician Release				Work Order Totals		
Buy Back ☐ Test FLT ☐	Tech Signature:	_	Tech#:	1	abor arts	75.00 20.50
Maintenance Release				TC	TAL:	95.50
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order.				Preliminary / Hidden Inspection Release		
	Signed:Station JX8R258Q . 237 N Helmer Roac		k, MI 49037	Dat	te: pector:	